

Known Errata in the 2011 Ohio Building Codes (Dec 2011)

The Board of Building Standards (BBS) staff, after filing the official rules that make up the Ohio building codes, occasionally finds errors in the rules and/or the publishers' copies of the codes. These known errors are listed in the following table for your reference. These errata require a BBS rule change and will be included in an upcoming public hearing tentatively scheduled for the fall of 2012.

Please contact a BBS technical staff member at (614) 644-2613 if you discover an error in any of the Ohio codes that are not shown on this list.

Ohio Building Code (OBC)		
Code Section	Description of Error	Action required to correct error
111.1.6	Reference should be to Section 102.8 (not 102.7)	BBS rule change
406.2.2	Reference should be to Chapter 11 and ICC A117.1 (not ADAAG)	BBS rule change
407.3.2, Exception	Reference should be to Section 1008.1.9.6 (not 1008.1.8.6.2)	BBS rule change
412.3.6	Reference should be to Chapter 11 and ICC A117.1 (not ADAAG)	BBS rule change
903.5	Reference should be to the <i>fire code</i> (not the International Fire Code)	BBS rule change
907.5.2	References should be to Chapter 11, ICC A117.1, and NFPA 72 (not ADAAG)	BBS rule change

907.5.2.2	Second sentence reference should be to Section 404 <u>of the fire code</u> (not to OBC Section 404 and not to the International Fire Code)	BBS rule change
3008.11.5	Reference should be to Chapter 11 and ICC A117.1 (not ADAAG)	BBS rule change
3008.13.1	Reference should be to <i>the Ohio Elevator Code</i> , Chapter 11, ICC A117.1, and NFPA 72 (not ADAAG)	BBS rule change
3008.13.2	Reference should be to <i>the Ohio Elevator Code</i> , Chapter 11, ICC A117.1, and NFPA 72 (not ADAAG)	BBS rule change
3501.4	ICC reference to IFC-09 should be deleted (all references to a fire code should now be to the “fire code”)	BBS rule change
Ohio Plumbing Code (OPC)		
Code Section	Description of Error	Action Required to Correct Error
ICC publication 1003.4 and Exception	The phrase “and in hydraulic elevator pits” should be deleted. The exception should be deleted in its entirety.	ICC should correct error and publish corrected code text