



Department of Commerce

Division of Industrial Compliance

John R. Kasich, Governor

Jacqueline T. Williams, Director

September 2017

Board of Building Standards Approved Continuing Education Course Listing

2017 BBS Course Listing
(by Sponsor)

| Course Number | Course Name | Sponsor | Contact Name | Phone | Email | Certifications (Hours) |
|---------------|---|---------------------------------------|-------------------|----------------|---------------------------|---|
| BBS2017-017 | NEC Requirements for Emerging Communication Technologies & Connectivity | Adequate Wiring Committee | Gina Reichard | (937) 264-3243 | greichardawc@aol.com | BO(2.0), MPE(2.0), EPE(2.0), BI(2.0), ESI(2.0) |
| BBS2017-450 | Basic Fire Alarm Seminar | AFAA | Thomas Hammerberg | (844) 438-2322 | admin@afaa.org | BO(7.0), MPE(7.0), EPE(7.0), BI(7.0), FPI(7.0), RBO(7.0), RPE(7.0), RBI(7.0) |
| BBS2017-447 | Fire Alarm Inspection & Testing – NFPA 72 2016 | AFAA | Thomas Hammerberg | (844) 438-2322 | admin@afaa.org | BO(7.0), MPE(7.0), EPE(7.0), BI(7.0), FPI(7.0), RBO(7.0), RPE(7.0), RBI(7.0) |
| BBS2017-448 | Fire Alarm Plan Review Seminar | AFAA | Thomas Hammerberg | (844) 438-2322 | admin@afaa.org | BO(7.0), MPE(7.0), EPE(7.0), BI(7.0), FPI(7.0), RBO(7.0), RPE(7.0), RBI(7.0) |
| BBS2017-334 | Significant Changes to NFPA 72-2016 (Campus Fire Safety Conference) | AFAA | Thomas Hammerberg | (844) 438-2322 | admin@afaa.org | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-451 | Understanding Fire Alarm Requirements of the 2015 IBC / OBC | AFAA | Thomas Hammerberg | (844) 438-2322 | admin@afaa.org | BO(7.0), MPE(7.0), EPE(7.0), BI(7.0), FPI(7.0), RBO(7.0), RPE(7.0), RBI(7.0) |
| BBS2017-449 | Users Guide to Simplifying NFPA 72 & the NEC | AFAA | Thomas Hammerberg | (844) 438-2322 | admin@afaa.org | BO(7.0), MPE(7.0), EPE(7.0), BI(7.0), FPI(7.0), RBO(7.0), RPE(7.0), RBI(7.0) |
| BBS2017-035 | Smoke & fire Curtains: Meeting Atrium Smoke Requirements | Air Control Products | Mike Hynes | (440) 526-3020 | mh@aircontrolproducts.com | BO(1.0), MPE(1.0), MI(1.0), BI(1.0), FPI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-034 | Smoke Containment at the Hoistway Opening | Air Control Products | Mike Hynes | (440) 526-3020 | mh@aircontrolproducts.com | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-387 | Engineered Wood A to Z | American Wood Council (James B Smith) | James Smith | (608) 635-6635 | jsmith@awc.org | BO(3.0), MPE(3.0), BI(3.0), RBO(3.0), RPE(3.0), RBI(3.0) |
| BBS2017-136 | 2011 Ohio Mechanical & Fuel Gas Code Highlights | Associated Consulting Solutions LLC | Jerry Flanik | (216) 256-3556 | skillbuilder64@aol.com | BI(3.0), BO(3.0), EPE(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-135 | 2011 OMC – Design, Plan Review & Inspection | Associated Consulting Solutions LLC | Jerry Flanik | (216) 256-3556 | skillbuilder64@aol.com | BI(3.0), BO(3.0), ESI(3.0), LPE(3.0), MPE(3.0), MI(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-137 | Automatic Sprinkler Systems: Requirements | Associated Consulting Solutions LLC | Jerry Flanik | (216) 256-3556 | skillbuilder64@aol.com | BI(3.0), BO(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-134 | Case Studies For Proper Plan Review & Inspection to Avoid Disaster | Associated Consulting Solutions LLC | Jerry Flanik | (216) 256-3556 | skillbuilder64@aol.com | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-399 | 2013 RCO (MANRCO) (Module 1) Chap. 2; Chap. 3, Part I (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), RBO(0.5), RPE(0.5), RBI(0.5) |
| BBS2017-400 | 2013 RCO (MANRCO) (Module 2) Chap. 3, Part II (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), RBO(0.5), RPE(0.5), RBI(0.5) |
| BBS2017-401 | 2013 RCO (MANRCO) (Module 3) Chap. 4 & 5 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), RBO(0.5), RPE(0.5), RBI(0.5) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|----------------|----------------|---------------------------|---|
| BBS2017-402 | 2013 RCO (MANRCO) (Module 4) Chap. 6 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), RBO(0.5), RPE(0.5), RBI(0.5) |
| BBS2017-403 | 2013 RCO (MANRCO) (Module 5) Chap. 7, 8, 9, 10 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), RBO(0.5), RPE(0.5), RBI(0.5) |
| BBS2017-404 | 2013 RCO (MANRCO) (Module 6) Chap. 11 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | RBO(0.5), RPE(0.5), RBI(0.5) |
| BBS2017-405 | 2013 RCO (MANRCO) (Module 7) Chap. 13, 15, 16, 17, 21 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), RBO(0.5), RPE(0.5), RBI(0.5), RMI(0.5) |
| BBS2017-406 | 2013 RCO (MANRCO) (Module 8) Chap. 24, 29, 34 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | ESI(0.5), MPE(0.5), RBO(0.5), RBI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-068 | 2017 BBS Board Meetings (Apr 14) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-071 | 2017 BBS Board Meetings (Aug 25) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-074 | 2017 BBS Board Meetings (Dec 15) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-066 | 2017 BBS Board Meetings (Jan 20) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0), BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0) |
| BBS2017-070 | 2017 BBS Board Meetings (Jul 14) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-067 | 2017 BBS Board Meetings (Mar 3) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|----------------|----------------|---------------------------|---|
| BBS2017-069 | 2017 BBS Board Meetings (May 26) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-073 | 2017 BBS Board Meetings (Nov 17) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-072 | 2017 BBS Board Meetings (Oct 6) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-128 | 2017 Mechanical Code Significant Changes Update (Joint Conference Only) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(2.0), MPE(2.0), MCPE(2.0), FPI(2.0), MI(2.0) |
| BBS2017-539 | 2017 NEC Update | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(6.0), MPE(6.0), EPE(6.0), ESI(6.0) |
| BBS2017-441 | Accessibility Modules - (Module 12) Customer Service Elements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-429 | Accessibility Modules (Module 1) Key Definitions For Accessibility (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-439 | Accessibility Modules (Module 10) Special Considerations (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-440 | Accessibility Modules (Module 11) Accessibility In Existing Buildings (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-430 | Accessibility Modules (Module 2) Basis For Technical Requirements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|----------------|----------------|---------------------------|---|
| BBS2017-431 | Accessibility Modules (Module 3) Key Concepts For Accessibility (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-432 | Accessibility Modules (Module 4) Exterior Accessible Route (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-433 | Accessibility Modules (Module 5) Interior Accessible Route (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-434 | Accessibility Modules (Module 6) Accessibility Entry & Egress (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | ESI(0.5), MI(0.5), NRIUI(0.5), RBI(0.5), RBO(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), PI(0.5) |
| BBS2017-435 | Accessibility Modules (Module 7A) Accessibility In Dwelling & Sleeping Units Scoping (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | ESI(0.5), MI(0.5), NRIUI(0.5), PI(0.5), RBI(0.5), RBO(0.5), RIUI(0.5), RMI(0.5), RPE(0.5) |
| BBS2017-436 | Accessibility Modules (Module 7B) Accessibility In Dwelling & Sleeping Units Technical 7B (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | ESI(0.5), MI(0.5), NRIUI(0.5), PI(0.5), RBI(0.5), RBO(0.5), RIUI(0.5), RMI(0.5), RPE(0.5) |
| BBS2017-437 | Accessibility Modules (Module 8) Accessibility In Recreational Facilities (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-438 | Accessibility Modules (Module 9) Accessibility Plumbing Fixture Requirements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-227 | BBS Updates | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-397 | BBS Updates - IU Inspector Training (5/18/17) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | NRIUI(2.0), RIUI(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|----------------|----------------|---------------------------|---|
| BBS2017-471 | Building on the Code Series: Accessibility Requirements in Ohio & Code Administration | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), FPI(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0) |
| BBS2017-472 | Building on the Code Series: Chapter 1 Code Administration | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-463 | Building on the Code Series: Code Concepts | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), FPI(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0) |
| BBS2017-476 | Building on the Code Series: Common Electrical Code Topics (Articles 445, 450, & 517) (Generators, Transformers & Transformer Vaults, & Healthcare Facilities) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(4.0), MPE(4.0), EPE(4.0), ESI(4.0), RBO(1.3), RPE(1.3) |
| BBS2017-475 | Building on the Code Series: Common Ohio Mechanical Code Topics – Kitchen Hoods | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), FPI(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0) |
| BBS2017-470 | Building on the Code Series: Fire Alarm System & Smoke Alarm Requirements For Residential Occupancies | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), FPI(3.0), MPE(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RPE(3.0) |
| BBS2017-474 | Building on the Code Series: Ohio Plumbing Code (OPC) & Venting Sections, Part 2 | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(4.0), MPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), RPE(4.0), RPI(4.0) |
| BBS2017-473 | Building on the Code Series: OPC Drains & Venting | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(4.0), MPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RIUI(4.0), RPE(4.0), RPI(4.0) |
| BBS2017-464 | Building on the Code Series: RCO – Chapter 3 Requirements | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | RBO(4.0), RPE(4.0), RBI(4.0), RMI(4.0) |
| BBS2017-465 | Building on the Code Series: RCO – Chapter 4 Requirements | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0), RMI(3.0) |
| BBS2017-466 | Building on the Code Series: RCO – Chapters 5, 6, & 8 | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), MPE(4.0), NRIUI(4.0), RBI(4.0), RBO(4.0), RIUI(4.0), RMI(4.0), RPE(4.0) |
| BBS2017-468 | Building on the Code Series: RCO – Electrical Requirements | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RIUI(3.0), RPE(3.0) |
| BBS2017-467 | Building on the Code Series: RCO – Plumbing Requirements | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|----------------|----------------|---------------------------|---|
| BBS2017-469 | Building on the Code Series: RCO – Residential Mechanical Requirements | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), MPE(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), MI(3.0) |
| BBS2017-123 | Chapter 1 Administration | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-132 | Chapter 1 Administration (Joint Conference) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-407 | Fire Protection Systems - (Module 1) General Introduction to Fire Protection Systems (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-416 | Fire Protection Systems (Module 10) Fire Protection System Inspection Process (OBC 108) (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), FPI(0.5), MI(0.5), ESI(0.5), NRIUI(0.5), RBO(0.5), RBI(0.5), RIUI(0.5) |
| BBS2017-408 | Fire Protection Systems (Module 2) Water-Based Suppression System Basics (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), FPI(0.5), MPE(0.5), NRIUI(0.5), RBI(0.5), RBO(0.5), RIUI(0.5), RPE(0.5) |
| BBS2017-409 | Fire Protection Systems (Module 3) Water-Based Suppression Systems-Part 2-Highlights of Code Requirements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), FPI(0.5), MPE(0.5), NRIUI(0.5), RBI(0.5), RBO(0.5), RIUI(0.5), RPE(0.5) |
| BBS2017-410 | Fire Protection Systems (Module 4) Special Hazard Suppression Systems & Highlights of Code Requirements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(0.5), MPE(0.5), BI(0.5), FPI(0.5), NRIUI(0.5) |
| BBS2017-411 | Fire Protection Systems (Module 5) Fire & Emergency Alarm Systems Basics (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), MPE(0.5), NRIUI(0.5), RBO(0.5), RIUI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-412 | Fire Protection Systems (Module 6) Fire & Emergency Alarm Systems-Part 2-Highlights of Code Requirements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), MPE(0.5), NRIUI(0.5), RBO(0.5), RIUI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-413 | Fire Protection Systems (Module 7) Control of Smoke & Highlights of Code Requirements (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(0.5), MPE(0.5), BI(0.5), FPI(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5) |
| BBS2017-414 | Fire Protection Systems (Module 8) Tying the Systems Together-Emergency Control Functions & Interfaces (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(0.5), MPE(0.5), BI(0.5), FPI(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|-----|----------------|----------------|---------------------------|---|
| BBS2017-415 | Fire Protection Systems (Module 9) Fire Protection System Plan Review Process (OBC 107) (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), EPE(0.5), MCPE(0.5), RBO(0.5), RPE(0.5) |
| BBS2017-338 | Fire Protection Systems: Plan Review, Testing, & Inspections | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-337 | Fire Protection Systems: Plan Review, Testing, & Inspections (FBOA) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-374 | Highlights 2017 Ohio Building Code (ALA Only) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-127 | Industrialized Units | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-133 | Inspector Skills Training (Joint Conference) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-348 | OBC Chapter 3 Updates (for the Fire Safety Inspectors 2017 Conference) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0) |
| BBS2017-540 | OBC Chapter 9 | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | FPI(1.5) |
| BBS2017-339 | Online Energy Code Training | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(3.0), BO(3.0), EPE(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-129 | Proposed OBC Fire Protection System Updates | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(1.0), MPE(1.0), MCPE(1.0), FPI(1.0), MI(1.0) |
| BBS2017-443 | Significant Changes to the 2012 IECC & ANSI / ASHRAE / IES Standard 90.1-2010 (Akron – 5/24/17) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0) |
| BBS2017-442 | Significant Changes to the 2012 IECC & ANSI / ASHRAE / IES Standard 90.1-2010 (Forest Park – 5/23/17) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|----------------|----------------|---------------------------|---|
| BBS2017-444 | Significant Changes to the 2012 IECC & ANSI / ASHRAE / IES Standard 90.1-2010 (Reynoldsburg – 5/25/17) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0) |
| BBS2017-377 | Significant Changes to the 2012 IECC and ANSI/ASHRAE/IES Standard 90.1-2010 (Dayton) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(4.0), MPE(4.0), MCPE(4.0), PPE(4.0), EPE(4.0), BI(4.0), MI(4.0), PI(4.0), ESI(4.0), NRIUI(4.0) |
| BBS2017-376 | Significant Changes to the 2012 IECC and ANSI/ASHRAE/IES Standard 90.1-2010 (Toledo) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(4.0), MCPE(4.0), MPE(4.0), PPE(4.0), EPE(4.0), BI(4.0), MI(4.0), PI(4.0), ESI(4.0), NRIUI(4.0) |
| BBS2017-536 | Significant Changes to the 2015 IBC | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(3.0), MPE(3.0), BI(3.0), FPI(3.0), NRIUI(3.0) |
| BBS2017-538 | Significant Changes to the 2015 IMC | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(1.5), MPE(1.5), MCPE(1.5), BI(1.5), MI(1.5) |
| BBS2017-537 | Significant Changes to the 2015 IPC | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(1.5), MPE(1.5), PPE(1.5), PI(1.5) |
| BBS2017-375 | Significant Changes to the Energy Conservation Code 2012 and ANSI/ASHRAE/IES Standard 90.1-2010 (Lorain) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BO(4.0), MPE(4.0), MCPE(4.0), PPE(4.0), EPE(4.0), BI(4.0), MI(4.0), PI(4.0), ESI(4.0), NRIUI(4.0) |
| BBS2017-417 | Wood Wall Bracing (Module 1) Load Path, Lateral Forces & Stiffened Wall (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-426 | Wood Wall Bracing (Module 10) Wall Bracing Examples 1 & 2 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-427 | Wood Wall Bracing (Module 11) Wall Bracing Example 3 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5), BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5) |
| BBS2017-428 | Wood Wall Bracing (Module 12) Wall Bracing Example 4 (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-418 | Wood Wall Bracing (Module 2) History of Wall Bracing & Limits (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|--------------------------|---------------------|----------------|---------------------------|---|
| BBS2017-419 | Wood Wall Bracing (Module 3) Braced Wall Lines (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-420 | Wood Wall Bracing (Module 4) Braced Wall Panels (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-421 | Wood Wall Bracing (Module 5) Intermittent Bracing Methods (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-422 | Wood Wall Bracing (Module 6) Continuous Sheathing Methods End Conditions (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-423 | Wood Wall Bracing (Module 7) Mixing Methods – Interior Finish – Joints Sufficient Length (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-424 | Wood Wall Bracing (Module 8) Connections Cripple Walls Foundations (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-425 | Wood Wall Bracing (Module 9) Simplified Wall Bracing (online) | BBS | Vicky Williams | (614) 644-2613 | vwilliams@com.state.oh.us | BI(0.5), BO(0.5), EPE(0.5), ESI(0.5), FPI(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5) |
| BBS2017-542 | Building Envelope Certified (online course) | BES Institute | Patricia Charleston | (877) 688-2374 | admin@besinstitute.com | BI(16.0), BO(16.0), MPE(16.0), RBI(16.0), RBO(16.0), RPE(16.0) |
| BBS2017-541 | Building Envelope Trained (online course) | BES Institute | Patricia Charleston | (877) 688-2374 | admin@besinstitute.com | BI(6.0), BO(6.0), MPE(6.0), RBI(6.0), RBO(6.0), RPE(6.0) |
| BBS2017-099 | Plans Examiner Roundtable Discussion (Apr 19) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | MPE(1.0), MCPE(1.0), EPE(1.0), PPE(1.0) |
| BBS2017-097 | Plans Examiner Roundtable Discussion (Feb 15) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | MPE(1.0), EPE(1.0), MCPE(1.0), PPE(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|---------------------------|-----------------|----------------|---------------------------|---|
| BBS2017-096 | Plans Examiner Roundtable Discussion (Jan 18) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | MPE(1.0), MCPE(1.0), EPE(1.0), PPE(1.0) |
| BBS2017-101 | Plans Examiner Roundtable Discussion (Jun 21) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0) |
| BBS2017-098 | Plans Examiner Roundtable Discussion (Mar 15) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0) |
| BBS2017-100 | Plans Examiner Roundtable Discussion (May 17) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0) |
| BBS2017-104 | Plans Examiner Roundtable Discussion (Nov 15) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0) |
| BBS2017-103 | Plans Examiner Roundtable Discussion (Oct 18) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0) |
| BBS2017-102 | Plans Examiner Roundtable Discussion (Sep 20) | BOCONEO - Paul Kowalczyk | Paul Kowalczyk | (216) 381-0400 | pkowalczyk@seuclid.com | EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0) |
| BBS2017-226 | Practical Inspection Techniques for Automatic Sprinkler Systems | BOCONEO (Philip Seyboldt) | Philip Seyboldt | (216) 701-1431 | pseyboldt@sbcglobal.net | BI(3.0), BO(3.0), FPI(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0), MI(3.0) |
| BBS2017-082 | Enforcement of the Code | BOCONEO (Raymond Sack) | Raymond Sack | (440) 943-7115 | rsack@cityofwickliffe.com | MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0), BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0) |
| BBS2017-108 | Electrical Inspectors Roundtable Discussion (Apr 19) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-106 | Electrical Inspectors Roundtable Discussion (Feb 15) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-105 | Electrical Inspectors Roundtable Discussion (Jan 18) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-110 | Electrical Inspectors Roundtable Discussion (Jun 21) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-107 | Electrical Inspectors Roundtable Discussion (Mar 15) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-109 | Electrical Inspectors Roundtable Discussion (May 17) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-113 | Electrical Inspectors Roundtable Discussion (Nov 15) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-112 | Electrical Inspectors Roundtable Discussion (Oct 18) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-111 | Electrical Inspectors Roundtable Discussion (Sep 20) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), EPE(1.0), ESI(1.0), RBO(1.0) |
| BBS2017-117 | Plumbing Inspectors Roundtable Discussion (Apr 19) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|--|----------------|----------------|-------------------------------------|--|
| BBS2017-115 | Plumbing Inspectors Roundtable Discussion (Feb 15) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-114 | Plumbing Inspectors Roundtable Discussion (Jan 18) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-119 | Plumbing Inspectors Roundtable Discussion (Jun 21) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-116 | Plumbing Inspectors Roundtable Discussion (Mar 15) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | RPE(1.0), RPI(1.0), BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0) |
| BBS2017-118 | Plumbing Inspectors Roundtable Discussion (May 17) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-122 | Plumbing Inspectors Roundtable Discussion (Nov 15) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-121 | Plumbing Inspectors Roundtable Discussion (Oct 18) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-120 | Plumbing Inspectors Roundtable Discussion (Sep 20) | BOCONEO / Michael Gero | Michael Gero | (440) 537-4548 | mjgero@sbcglobal.net | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-259 | Fireplace, Wood & Coal Heaters (Condensed) | Bures Consultants Inc | Robert Bures | (440) 816-0525 | info@buresconsultantsinc.com | BI(3.0), BO(3.0), FPI(3.0), MPE(3.0), MI(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RPE(3.0) |
| BBS2017-260 | Fireplace, Wood & Coal Heaters (Extended) | Bures Consultants Inc | Robert Bures | (440) 816-0525 | info@buresconsultantsinc.com | BI(7.0), BO(7.0), FPI(7.0), MPE(7.0), MI(7.0), NRIUI(7.0), RBI(7.0), RBO(7.0), RIUI(7.0), RPE(7.0) |
| BBS2017-321 | Code Calculations – Part I | Central Electric Inspection Bureau | John Grivensky | (330) 744-5238 | centralelectricinspection@yahoo.com | BO(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-322 | Code Calculations – Part II | Central Electric Inspection Bureau | John Grivensky | (330) 744-5238 | centralelectricinspection@yahoo.com | BO(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-257 | SOARES 2014 – Grounding & Bonding | Central Electric Inspection Bureau | John Grivensky | (330) 744-5238 | centralelectricinspection@yahoo.com | BO(5.0), MPE(5.0), EPE(5.0), ESI(5.0) |
| BBS2017-305 | An Overview of NFPA 70 (NEC)-Apr. 24 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-309 | An Overview of NFPA 70 (NEC)-Aug. 28 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-313 | An Overview of NFPA 70 (NEC)-Dec. 18 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-303 | An Overview of NFPA 70 (NEC)-Feb. 27 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|--|-----------------|----------------|-----------------------|---|
| BBS2017-302 | An Overview of NFPA 70 (NEC)-Jan. 30 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-308 | An Overview of NFPA 70 (NEC)-Jul. 31 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-307 | An Overview of NFPA 70 (NEC)-Jun. 26 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-304 | An Overview of NFPA 70 (NEC)-Mar. 27 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-306 | An Overview of NFPA 70 (NEC)-May 22 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-312 | An Overview of NFPA 70 (NEC)-Nov. 27 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-311 | An Overview of NFPA 70 (NEC)-Oct. 30 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-310 | An Overview of NFPA 70 (NEC)-Sep. 25 | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-157 | Navigating the Plumbing Code – Plumbing Plan Examiner Test Preparation (Joint Conference) | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BI(2.0), BO(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-504 | Occupied Roofs & Patios | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-383 | Overview of the Plan Approval Process | City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky) | Bob Schutz | (614) 395-9689 | rjschutz@columbus.gov | BO(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-363 | Round Table Discussion of Mechanical & Residential Codes | City of Toledo - Charles Sutphin | Charles Sutphin | (419) 345-7010 | chazmsut@bex.net | BI(2.5), BO(2.5), FPI(2.5), MPE(2.5), MI(2.5), MCPE(2.5), RBI(2.5), RBO(2.5), RMI(2.5), RPE(2.5) |
| BBS2017-237 | Administering OBBC; BBS Updates; Understanding the Code (May 2-3, 2017) | Cleveland Plumbing Industry Promotion | Thomas Wanner | (216) 459-0770 | twanner@mapic.org | BI(10.0), BO(10.0), EPE(10.0), FPI(10.0), LPE(10.0), MPE(10.0), MI(10.0), MCPE(10.0), NRIUI(10.0), PI(10.0), PPE(10.0), RBI(10.0), RBO(10.0), REPE(10.0), RIUI(10.0), RMI(10.0), RPE(10.0), RPI(10.0) |
| BBS2017-238 | Administering OBBC; BBS Updates; Understanding the Code (October 3-4, 2017) | Cleveland Plumbing Industry Promotion | Thomas Wanner | (216) 459-0770 | twanner@mapic.org | BI(10.0), BO(10.0), EPE(10.0), FPI(10.0), LPE(10.0), MPE(10.0), MI(10.0), MCPE(10.0), NRIUI(10.0), PI(10.0), PPE(10.0), RBI(10.0), RBO(10.0), REPE(10.0), RIUI(10.0), RMI(10.0), RPE(10.0), RPI(10.0) |
| BBS2017-278 | COCOA Code Consistency Committee Roundtable (Apr 17) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|----------------------|--------------|----------------|-----------------------|--|
| BBS2017-282 | COCOA Code Consistency Committee Roundtable (Aug 16) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-286 | COCOA Code Consistency Committee Roundtable (Dec 20) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-276 | COCOA Code Consistency Committee Roundtable (Feb 15) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-275 | COCOA Code Consistency Committee Roundtable (Jan 18) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-281 | COCOA Code Consistency Committee Roundtable (Jul 19) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-280 | COCOA Code Consistency Committee Roundtable (Jun 21) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-277 | COCOA Code Consistency Committee Roundtable (Mar 15) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-279 | COCOA Code Consistency Committee Roundtable (May 17) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|---------------------------------|------------------|----------------|-------------------------------|---|
| BBS2017-285 | COCOA Code Consistency Committee Roundtable (Nov 15) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-284 | COCOA Code Consistency Committee Roundtable (Oct 18) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-283 | COCOA Code Consistency Committee Roundtable (Sep 20) | COCOA (Mike Poirier) | Mike Poirier | (614) 830-2045 | cocoaonline@gmail.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-188 | What You Need to Know: Introduction to Fire Sprinklers (Day 1) | Colerain Fire Department | Mark Walsh | (513) 245-6505 | mwalsh@colerain.org | BO(6.0), MPE(6.0), BI(6.0), FPI(6.0) |
| BBS2017-189 | What You Need to Know: Introduction to Fire Sprinklers (Day 2) | Colerain Fire Department | Mark Walsh | (513) 245-6505 | mwalsh@colerain.org | BO(6.0), MPE(6.0), BI(6.0), FPI(6.0) |
| BBS2017-184 | Electronic Plan Review Process for Building Departments (Joint Conference) | Columbus Bldg & Zoning Services | Sam Cronk | (614) 645-2389 | sdcronk@columbus.gov | BO(2.0), EPE(2.0), MPE(2.0), MCPE(2.0), PPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-183 | Understanding How to Use the NEC (Joint Conference) | Columbus Bldg & Zoning Services | Sam Cronk | (614) 645-2389 | sdcronk@columbus.gov | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-352 | Corrugated Stainless Steel Tubing (CSST)- Putting Product Safety Standards to the Test | CSA Group | Valerie Madarasz | (216) 524-4990 | valerie.madarasz@csagroup.org | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-228 | Navigating the Product Certification Maze | CSA Group | Valerie Madarasz | (216) 524-4990 | valerie.madarasz@csagroup.org | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-271 | Navigating the Product Certification Maze | CSA Group | Valerie Madarasz | (216) 524-4990 | valerie.madarasz@csagroup.org | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-365 | Chapter 3 & 5-2016 Updates & the 2017 Proposed Updates | Dabdoub & Associates LLC | Majed Dabdoub | (513) 208-2056 | majed@dabdoub.net | BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|--------------------------|---------------|----------------|---------------------------|--|
| BBS2017-018 | OBC Means of Egress Chapter 10 / 2009 IBC (For SWOBOA) | Dabdoub & Associates LLC | Majed Dabdoub | (513) 208-2056 | majed@dabdoub.net | BI(2.0), BO(2.0), MPE(2.0), EPE(2.0), PPE(2.0), MCPE(2.0) |
| BBS2017-287 | Significant Changes in 2017 NEC (Session 1) | Dayton Electrical JATC | Eric Gray | (937) 264-2052 | dbrooksjatc@sbcglobal.net | BO(6.0), EPE(6.0), ESI(6.0), MPE(6.0), RBO(6.0), RPE(6.0) |
| BBS2017-288 | Significant Changes in 2017 NEC (Session 2) | Dayton Electrical JATC | Eric Gray | (937) 264-2052 | dbrooksjatc@sbcglobal.net | BO(6.0), EPE(6.0), ESI(6.0), MPE(6.0), RBO(6.0), RPE(6.0) |
| BBS2017-499 | Analysis of Changes 2017 NEC, Part I | DIC/BCC | Paul Wilson | (614) 728-5293 | | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), ESI(5.0) |
| BBS2017-500 | Analysis of Changes 2017 NEC, Part II | DIC/BCC | Paul Wilson | (614) 728-5293 | | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), ESI(5.0) |
| BBS2017-395 | Basic Overview of Roof Assemblies and Rooftop Structures | DIC/BCC | Paul Wilson | (614) 728-5293 | | BO(4.0), MPE(4.0), BI(4.0), RBO(4.0), RPE(4.0), RBI(4.0) |
| BBS2017-492 | The Inspection Process (Aug) | DIC/BCC | Paul Wilson | (614) 728-5293 | | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0) |
| BBS2017-496 | The Inspection Process (Dec) | DIC/BCC | Paul Wilson | (614) 728-5293 | | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0) |
| BBS2017-495 | The Inspection Process (Nov) | DIC/BCC | Paul Wilson | (614) 728-5293 | | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0) |
| BBS2017-494 | The Inspection Process (Oct) | DIC/BCC | Paul Wilson | (614) 728-5293 | | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0) |
| BBS2017-493 | The Inspection Process (Sept) | DIC/BCC | Paul Wilson | (614) 728-5293 | | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0) |
| BBS2017-381 | DIC Plumbing Module Chapter 10 Traps, Interceptors and Separators | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(2.0), MPE(2.0), PPE(2.0), BI(2.0), MI(2.0), PI(2.0), RBO(2.0), RPE(2.0), RBI(2.0), RPI(2.0) |
| BBS2017-032 | DIC Plumbing Module: (Chapter 12) (Medical Gas Part I) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-033 | DIC Plumbing Module: (Chapter 12) (Medical Gas Part II) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-029 | DIC Plumbing Module: Chapter 11 (Storm & Roof Drainage) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-019 | DIC Plumbing Module: Chapter 5 (Water Heaters) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-022 | DIC Plumbing Module: Chapter 6 (Backflow 101) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-021 | DIC Plumbing Module: Chapter 6 (Backflow) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-020 | DIC Plumbing Module: Chapter 6 (Water Systems) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|--------------------------|-----------------|----------------|------------------------|---|
| BBS2017-023 | DIC Plumbing Module: Chapter 7 (Sanitary Drainage) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-024 | DIC Plumbing Module: Chapter 8 (Indirect Waste Systems) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-025 | DIC Plumbing Module: Chapter 9 (Vent Systems) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-030 | DIC Plumbing Module: Code Games (OPC Chapters 2-11 Review) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-026 | DIC Plumbing Module: Drawing Plumbing Isometrics (Chapters 7 & 9) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-028 | DIC Plumbing Module: FOG (Chapters 7, 9, & 10) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-364 | DIC Plumbing Module: OPC Code Updates | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(2.0), MPE(2.0), PPE(2.0), PI(2.0), NRIUI(2.0), RBO(2.0), RPE(2.0), RIUI(2.0) |
| BBS2017-081 | DIC Plumbing Module: Plumbing Fixtures ADA Requirements | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(1.0), MPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0) |
| BBS2017-080 | DIC Plumbing Module: Plumbing Fixtures: Chapter 4 (Part 1) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(1.0), MPE(1.0), PI(1.0), PPE(1.0), RBO(1.0), RIUI(1.0), RPE(1.0), NRIUI(1.0) |
| BBS2017-027 | DIC Plumbing Module: Plumbing Plan Review (OPC Chapters 2-11) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BI(2.0), BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-031 | DIC Plumbing Module: Rain Water Harvesting (OPC Chapter 11) | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(2.0), MPE(2.0), MI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0), RPI(2.0), BI(2.0) |
| BBS2017-531 | DIC/BCC Plumbing Course (7/19/17) AM | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(2.0), MPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBO(2.0), RIUI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-532 | DIC/BCC Plumbing Course (7/19/17) PM | DIC/BCC Plumbing Section | Jack Soma | (614) 644-3153 | jack.soma@com.ohio.gov | BO(2.0), MPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBO(2.0), RIUI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-369 | Air For Combustion & Ventilation of Natural Gas Appliances | Dominion East Ohio Gas | Donald MacBride | (216) 736-6697 | dona149@dom.com | BI(2.0), BO(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-368 | Corrugated Stainless Steel Tubing (CSST) Gas Tubing System | Dominion East Ohio Gas | Donald MacBride | (216) 736-6697 | dona149@dom.com | BI(2.0), BO(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|---------------------------------------|-------------------|----------------|-----------------------------------|---|
| BBS2017-366 | Natural Gas Fundamentals | Dominion East Ohio Gas | Donald MacBride | (216) 736-6697 | dona149@dom.com | BI(2.0), BO(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-151 | Review of the IFGC (Joint Conference only) | Dominion East Ohio Gas | Donald MacBride | (216) 736-6697 | dona149@dom.com | BI(3.0), BO(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-152 | Review of the IFGC (Outside of Conference) | Dominion East Ohio Gas | Donald MacBride | (216) 736-6697 | dona149@dom.com | BI(3.0), BO(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-367 | Sizing Category I Venting Systems | Dominion East Ohio Gas | Donald MacBride | (216) 736-6697 | dona149@dom.com | BI(2.0), BO(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-454 | 2017 NEC Electrical Requirements in Health Care Facilities | Electrical League of Ohio | Terri Hanna-Wiehn | (440) 333-5040 | terrihanna-wiehn@sbcglobal.net | BO(4.0), MPE(4.0), EPE(4.0), BI(4.0), FPI(4.0), RBI(4.0), RIUI(4.0), ESI(4.0) |
| BBS2017-382 | 2017 NEC Update | Electrical League of Ohio | Terri Hanna-Wiehn | (440) 333-5040 | terrihanna-wiehn@sbcglobal.net | BO(4.5), BI(4.5), RBO(4.5), RPE(4.5), RBI(4.5), ESI(4.5) |
| BBS2017-350 | National Electrical Code Review | Electrical League of Ohio | Terri Hanna-Wiehn | (440) 333-5040 | terrihanna-wiehn@sbcglobal.net | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), ESI(5.0) |
| BBS2017-264 | Fire Risk Assessments | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), BI(1.0), FPI(1.0) |
| BBS2017-266 | NFPA 72 - Testing & Inspections, Can You Self Perform Them? | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), BI(1.0), FPI(1.0) |
| BBS2017-267 | Overview of: Water Based Fire Protection Testing Standard - NFPA 25 (08) | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-265 | Prioritizing Fire Protection & Sprinkler Upgrades With Limited Budgets While Planning for The Long Term | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), BI(1.0), FPI(1.0) |
| BBS2017-335 | Protecting Fire Protection Systems (Campus Fire Safety Conference) | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-269 | Stationary Fire Pumps 100 – Installation & Maintenance Basics | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-268 | Two Way Radio Enhancement Systems, The Basics You Need to Know | Fire Code Academy | Randall Hormann | (800) 771-3403 | randyh@firecodeacademy.com | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-460 | Firestopping – Plan Review & Inspections | Fire Containment Training Service LLC | Brice Miller | (970) 223-4985 | brice@firecontainmenttraining.com | BI(4.0), BO(4.0), EPE(4.0), ESI(3.0), FPI(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|---------------------------------------|----------------|----------------|-----------------------------------|---|
| BBS2017-457 | Firestopping – Plan Review & Inspections (1 hr) | Fire Containment Training Service LLC | Brice Miller | (970) 223-4985 | brice@firecontainmenttraining.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-458 | Firestopping – Plan Review & Inspections (2 hrs) | Fire Containment Training Service LLC | Brice Miller | (970) 223-4985 | brice@firecontainmenttraining.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-459 | Firestopping – Plan Review & Inspections (3 hrs) | Fire Containment Training Service LLC | Brice Miller | (970) 223-4985 | brice@firecontainmenttraining.com | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-461 | Firestopping – Plan Review & Inspections (6 hrs except ESI (3 hrs) | Fire Containment Training Service LLC | Brice Miller | (970) 223-4985 | brice@firecontainmenttraining.com | BI(6.0), BO(6.0), EPE(6.0), ESI(3.0), FPI(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0) |
| BBS2017-462 | Firestopping – Plan Review & Inspections (7 hrs except ESI (3 hrs) | Fire Containment Training Service LLC | Brice Miller | (970) 223-4985 | brice@firecontainmenttraining.com | BI(7.0), BO(7.0), EPE(7.0), ESI(3.0), FPI(7.0), LPE(7.0), MPE(7.0), MI(7.0), MCPE(7.0), NRIUI(7.0), PI(7.0), PPE(7.0), RBI(7.0), RBO(7.0), REPE(7.0), RIUI(7.0), RMI(7.0), RPE(7.0), RPI(7.0) |
| BBS2017-079 | Ohio Automatic Sprinkler & Standpipe Systems (Online) | Fire Tech Productions Inc | Mary Harbach | (937) 434-3473 | info@firetech.com | BO(5.0), MPE(5.0), BI(5.0), FPI(5.0) |
| BBS2017-077 | Ohio Fire Alarm & Detection Equipment (Online) | Fire Tech Productions Inc | Mary Harbach | (937) 434-3473 | info@firetech.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), FPI(3.0) |
| BBS2017-078 | Ohio Fire Pumps (Online) | Fire Tech Productions Inc | Mary Harbach | (937) 434-3473 | info@firetech.com | BO(4.0), MPE(4.0), BI(4.0), FPI(4.0) |
| BBS2017-076 | Ohio Fire Service Mains (Online) | Fire Tech Productions Inc | Mary Harbach | (937) 434-3473 | info@firetech.com | BO(3.0), MPE(3.0), PPE(3.0), BI(3.0), FPI(3.0), PI(3.0) |
| BBS2017-075 | Ohio Portable Fire Extinguishers (Online) | Fire Tech Productions Inc | Mary Harbach | (937) 434-3473 | info@firetech.com | BO(3.0), MPE(3.0), BI(3.0), FPI(3.0) |
| BBS2017-142 | Monthly Seminars/Meetings (Apr 17) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-147 | Monthly Seminars/Meetings (Dec 18) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-140 | Monthly Seminars/Meetings (Feb 27) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-139 | Monthly Seminars/Meetings (Jan 23) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-141 | Monthly Seminars/Meetings (Mar 20) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-143 | Monthly Seminars/Meetings (May 15) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-146 | Monthly Seminars/Meetings (Nov 20) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-145 | Monthly Seminars/Meetings (Oct 16) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-144 | Monthly Seminars/Meetings (Sep 18) | GCEA | Terrence Eibel | (859) 512-5244 | gcea01@fuse.net | BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), RPE(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|---------------------------------|---------------------|----------------|-----------------------------|---|
| BBS2017-229 | BBS2017- Construction Documents & the UDS | Grusenmeyer & Associates, Inc | Jeffrey Grusenmeyer | (440) 333-1165 | jagarch@wowway.com | BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-388 | Building Dept. / Fire Dept. Relationships & Responsibilities | Grusenmeyer & Associates, Inc | Jeffrey Grusenmeyer | (440) 333-1165 | jagarch@wowway.com | BO(2.0), MPE(2.0), PPE(2.0), EPE(2.0), MCPE(2.0), BI(2.0), FPI(2.0), MI(2.0), PI(2.0), NRIUI(2.0), RBO(2.0), RPE(2.0), RBI(2.0), RMI(2.0), RIUI(2.0), ESI(2.0) |
| BBS2017-230 | Building Physics & the Rain Screen Principle | Grusenmeyer & Associates, Inc | Jeffrey Grusenmeyer | (440) 333-1165 | jagarch@wowway.com | BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-231 | Principles of Materials I – Concrete | Grusenmeyer & Associates, Inc | Jeffrey Grusenmeyer | (440) 333-1165 | jagarch@wowway.com | BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0) |
| BBS2017-324 | Principles of Materials II – Wood | Grusenmeyer & Associates, Inc | Jeffrey Grusenmeyer | (440) 333-1165 | jagarch@wowway.com | BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-446 | Designing for Accessibility Under ADA Standards & the IBC (course does not cover OBC) | HalfMoon Education Inc | Doug Chapman | (715) 835-5900 | doug@halfmoonseminars.org | BO(6.5), BI(6.5), RBO(6.5), RPE(6.5), RBI(6.5) |
| BBS2017-392 | Legionella-Legionnaires Disease in Relation to Plumbing Systems | Hamilton County Health District | Lisa Humble | (513) 946-7851 | lisa.humble@hamilton-co.org | BO(1.5), MPE(1.5), PI(1.5), PPE(1.5) |
| BBS2017-393 | Ohio Plumbing Code Amendment Group 92 | Hamilton County Health District | Lisa Humble | (513) 946-7851 | lisa.humble@hamilton-co.org | PPE(1.5), PI(1.5), BO(1.5), MPE(1.5), RBO(1.5), RPE(1.5) |
| BBS2017-394 | Significant Changes to the International Plumbing, Mechanical, and Fuel Gas Code | Hamilton County Health District | Lisa Humble | (513) 946-7851 | lisa.humble@hamilton-co.org | BO(1.5), MPE(1.5), RBO(1.5), RPE(1.5), MCPE(1.5), BI(1.5), PPE(1.5), MI(1.5) |
| BBS2017-549 | NEC Article 695 | Herbert Porter | Herbert Porter | (330) 573-8723 | weilerot@gmail.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MCPE(2.0) |
| BBS2017-225 | A Look At Wood Use In All Types Of Construction | Hoover Treated Wood Products | Jim Gogolski | (706) 990-8963 | jjgogolski@frtw.com | BI(4.0), BO(4.0), EPE(4.0), FPI(4.0), LPE(4.0), MPE(4.0), NRIUI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RPE(4.0) |
| BBS2017-223 | Fire-Retardant Treated Wood & The Building Code (Basic) | Hoover Treated Wood Products | Jim Gogolski | (706) 990-8963 | jjgogolski@frtw.com | BI(1.0), BO(1.0), EPE(1.0), FPI(1.0), LPE(1.0), MPE(1.0), NRIUI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RPE(1.0) |
| BBS2017-149 | Fire-Retardant Treated Wood & the Building Code (Extended) (Joint Conference only) | Hoover Treated Wood Products | Jim Gogolski | (706) 990-8963 | jjgogolski@frtw.com | BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), LPE(2.0), MPE(2.0), NRIUI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RPE(2.0) |
| BBS2017-150 | Fire-Retardant Treated Wood & the Building Code (Extended) (outside of Conference) | Hoover Treated Wood Products | Jim Gogolski | (706) 990-8963 | jjgogolski@frtw.com | BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), LPE(2.0), MPE(2.0), NRIUI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RPE(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|-----------------------------------|---------------|----------------|---------------------------|--|
| BBS2017-224 | Wood Use In The IBC & Recognition Of Fire-Retardant Treated Wood | Hoover Treated Wood Products | Jim Gogolski | (706) 990-8963 | jjgogolski@frtw.com | BI(3.0), BO(3.0), EPE(3.0), FPI(3.0), LPE(3.0), MPE(3.0), NRIUI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RPE(3.0) |
| BBS2017-452 | Continuous Insulation: Code compliance & the NFPA 285 IN Commercial Wall Assemblies | Hunter Panels | Mary Schenker | (207) 271-1062 | mary.schenker@hpanels.com | BO(1.0), BI(1.0), FPI(1.0) |
| BBS2017-314 | Continuous Insulation: Code Compliance & The NFPA 285 in Commercial Wall Assemblies | Hunter XCI | Grant Stahl | (614) 430-0303 | abby@engineeredsys.com | BO(1.0), MPE(1.0), BI(1.0) |
| BBS2017-295 | IAEI Analysis of Changes – 2017 NEC (Apr 25) (Session 3) | IAEI - Akron Division (Tom Moore) | Tom Moore | (330) 289-7932 | tmoore1767@aol.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-293 | IAEI Analysis of Changes – 2017 NEC (Feb 28) (Session 1) | IAEI - Akron Division (Tom Moore) | Tom Moore | (330) 289-7932 | tmoore1767@aol.com | BI(2.0), BO(2.0), EPE(2.0), MPE(2.0), RBO(2.0), RPE(2.0), ESI(2.0) |
| BBS2017-298 | IAEI Analysis of Changes – 2017 NEC (Jul 25) (Session 6) | IAEI - Akron Division (Tom Moore) | Tom Moore | (330) 289-7932 | tmoore1767@aol.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-297 | IAEI Analysis of Changes – 2017 NEC (Jun 27) (Session 5) | IAEI - Akron Division (Tom Moore) | Tom Moore | (330) 289-7932 | tmoore1767@aol.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-294 | IAEI Analysis of Changes – 2017 NEC (Mar 28) (Session 2) | IAEI - Akron Division (Tom Moore) | Tom Moore | (330) 289-7932 | tmoore1767@aol.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-296 | IAEI Analysis of Changes – 2017 NEC (May 23) (Session 4) | IAEI - Akron Division (Tom Moore) | Tom Moore | (330) 289-7932 | tmoore1767@aol.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-175 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Apr 13) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-181 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Dec14) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-173 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Feb 9) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-172 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Jan 12) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-177 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Jun 8) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-174 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Mar 9) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-176 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (May 11) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-180 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Nov 9) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-179 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Oct 12) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-178 | 2014 / 2017 NEC Review / IAEI Monthly Meeting (Sep 14) | IAEI - Central Ohio Division | Ralph Hoffman | (740) 625-6575 | r.hoffman@ieee.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|-------------------------|-----------------|----------------|-------------------------|---|
| BBS2017-351 | 2014 NEC & RCO 314/315 Smoke Detector & Carbon Monoxide Alarm Requirements | IAEI - NW Division | Michael Farrell | (419) 213-2981 | mfarrell@co.lucas.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), RBI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-534 | 112 Annual Meeting Western Section IAEI | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(17.0), EPE(17.0), ESI(17.0), MPE(17.0), RPE(17.0), RBO(17.0) |
| BBS2017-153 | 2017 NEC – Analysis of Changes (Part 1 – Chapters 1-4) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(6.0), MPE(6.0), EPE(6.0), ESI(6.0), RBO(6.0), RPE(6.0) |
| BBS2017-154 | 2017 NEC – Analysis of Changes (Part 2 – Chapters 5-9) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(6.0), MPE(6.0), EPE(6.0), ESI(6.0), RBO(6.0), RPE(6.0) |
| BBS2017-391 | 2017 NEC - Analysis of Changes / 90th Ohio Chapter IAEI Annual Education Conference | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(4.0), MPE(4.0), EPE(4.0), RBO(4.0), RPE(4.0), ESI(4.0) |
| BBS2017-478 | 2017 NEC Review “Front to Back” Analysis & Changes, Part 1 (Chapters 1-3) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(7.5), MPE(7.5), EPE(7.5), ESI(7.5), RBO(7.5) |
| BBS2017-479 | 2017 NEC Review “Front to Back” Analysis & Changes, Part 2 (Chapters 3-5) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(7.5), MPE(7.5), EPE(7.5), ESI(7.5), RBO(7.5) |
| BBS2017-480 | 2017 NEC Review “Front to Back” Analysis & Changes, Part 3 (Chapters 5, 6) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(7.5), MPE(7.5), EPE(7.5), ESI(7.5), RBO(7.5) |
| BBS2017-481 | 2017 NEC Review “Front to Back” Analysis & Changes, Part 4 (Chapters 7-9) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(7.5), MPE(7.5), EPE(7.5), ESI(7.5), RBO(7.5) |
| BBS2017-094 | Monthly Meeting- Approved Testing Agencies (Nov 8) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0), MPE(2.0) |
| BBS2017-087 | Monthly Meeting- Fairs / Carnivals (Mar 8) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-089 | Monthly Meeting -Field Procedures (May 10) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-090 | Monthly Meeting -Grounding & Bonding (June14) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-085 | Monthly Meeting -Hazardous Locations (Jan 11) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-086 | Monthly Meeting -Health Care Facilities (Feb 8) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-088 | Monthly Meeting -Pools / Spas (Apr 12) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-095 | Monthly Meeting -Residential Wiring Methods (Dec 13) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-091 | Monthly Meeting -Separately Derived Systems (Aug 9) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0), MPE(2.0) |
| BBS2017-092 | Monthly Meeting -Sign / Outline Lighting (Sept 13) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-093 | Monthly Meetings -Services (Oct 11) | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-378 | Navigating the NEC/90th Ohio Chapter IAEI Annual Education Conference | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(1.0), MPE(1.0), EPE(1.0), BI(1.0), ESI(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|---------------------------------|----------------|----------------|------------------------|--|
| BBS2017-390 | Photovoltaic Overview / 90th Ohio Chapter IAEI Annual Education Conference | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(1.5), MPE(1.5), EPE(1.5), MI(1.5), RBO(1.5), RPE(1.5) |
| BBS2017-379 | Series Rating/SCCR/90th Ohio Chapter IAEI Annual Education Conference | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(1.0), MPE(1.0), EPE(1.0), BI(1.0), FPI(1.0), RBO(1.0), RPE(1.0), RBI(1.0), ESI(1.0) |
| BBS2017-380 | Underwriters Laboratory / Field Evaluations / 90th Ohio Chapter IAEI Annual Education Conference | IAEI - SW Ohio Division | Lorenzo Adam | (513) 229-8520 | ladam@masonoh.org | BO(1.5), MPE(1.5), EPE(1.5), BI(1.5), RBO(1.5), REPE(1.5), RBI(1.5), ESI(1.5) |
| BBS2017-051 | 2014 NEC Course (Session 1 – Intro to the NEC) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-060 | 2014 NEC Course (Session 10 – Review of Articles 684-Annex D) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-052 | 2014 NEC Course (Session 2 – Review of Articles 90-230) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-053 | 2014 NEC Course (Session 3 – Review of Articles 225-240) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-054 | 2014 NEC Course (Session 4 – Review of Articles 250-310) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-055 | 2014 NEC Course (Session 5 – Review of Articles 312-390) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-056 | 2014 NEC Course (Session 6 – Review of Articles 392-427) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-057 | 2014 NEC Course (Session 7 – Review of Articles 430-505) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-058 | 2014 NEC Course (Session 8 – Review of Articles 510-625) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), RBO(3.0), RPE(3.0), MPE(3.0) |
| BBS2017-059 | 2014 NEC Course (Session 9 – Review of Articles 626-680) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-037 | Analysis of Changes to the 2014 NEC (Session 1 –Review of Articles 90-240) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(5.0), MPE(5.0), EPE(5.0), ESI(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-038 | Analysis of Changes to the 2014 NEC (Session 2 – Review of Articles 250-312) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(5.0), MPE(5.0), EPE(5.0), ESI(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-039 | Analysis of Changes to the 2014 NEC (Session 3 –Review of Articles 314-422) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(5.0), MPE(5.0), EPE(5.0), ESI(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-040 | Analysis of Changes to the 2014 NEC (Session 4 –Review of Articles 424-830) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(5.0), MPE(5.0), EPE(5.0), ESI(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-041 | Analysis of Code Changes to the 2014 NEC (Session 1 – Intro to NEC 2014) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), MPE(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-050 | Analysis of Code Changes to the 2014 NEC (Session 10 — Review of Articles 550-830) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-042 | Analysis of Code Changes to the 2014 NEC (Session 2 — Review of Articles 90-230) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-043 | Analysis of Code Changes to the 2014 NEC (Session 3 — Review of Article 225-240) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|---------------------------------|----------------|----------------|------------------------|---|
| BBS2017-044 | Analysis of Code Changes to the 2014 NEC (Session 4 -- Review of Article 250) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-045 | Analysis of Code Changes to the 2014 NEC (Session 5 -- Review of Articles 310-312) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0), MPE(2.0) |
| BBS2017-046 | Analysis of Code Changes to the 2014 NEC (Session 6 -- Review of Articles 314-338) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-047 | Analysis of Code Changes to the 2014 NEC (Session 7 -- Review of Articles 344-400) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-048 | Analysis of Code Changes to the 2014 NEC (Session 8 -- Review of Articles 404-422) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-049 | Analysis of Code Changes to the 2014 NEC (Session 9 -- Review of Articles 424-525) | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-036 | Article 250 -- 2014 NEC | IAEI - Western Reserve Division | Joseph Cenzori | (440) 537-0320 | ampy2000@sbcglobal.net | BO(3.0), MPE(3.0), EPE(3.0), ESI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-477 | 2012 ICC Commercial Kitchen Hoods | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-319 | 2012 IECC (Commercial) Update | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(2.0), BO(2.0), EPE(2.0), LPE(2.0), MPE(2.0), MII(2.0), MCPE(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-509 | 2015 IBC Accessibility & Usability For Commercial Buildings | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(6.0), BO(6.0), EPE(6.0), FPI(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0) |
| BBS2017-315 | 2015 IBC Accessible Means of Egress | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-316 | 2015 IBC Allowable Heights & Areas | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-317 | 2015 IBC Fire & Life Safety Principles | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), FPI(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0) |
| BBS2017-521 | 2015 IBC Multifamily Dwellings | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(3.0), BI(3.0), RBO(3.0), RBI(3.0) |
| BBS2017-318 | 2015 IBC Significant Changes | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), FPI(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----|--------------|----------------|---------------------|---|
| BBS2017-389 | 2015 IBC Significant Changes | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | LPE(4.0), RPI(4.0), BO(4.0), MPE(4.0), PPE(4.0), EPE(4.0), MCPE(4.0), BI(4.0), FPI(4.0), MI(4.0), PI(4.0), NRIUI(4.0), RBO(4.0), RPE(4.0), RBI(4.0), RMI(4.0), RIUI(4.0), ESI(4.0) |
| BBS2017-320 | 2015 IPC & IMC Significant Changes | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-511 | Assessment of Alternative Materials & Methods of Construction | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(1.5), BI(1.5), RBO(1.5), RBI(1.5) |
| BBS2017-487 | B2 – Commercial Building Inspector Certification Test Academy (3.5-day course) | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(21.0) |
| BBS2017-524 | Best Practices For Design & Permitting Solar PV Systems | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MCPE(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RMI(1.5), RPI(1.5) |
| BBS2017-483 | Best Practices: Lessons Learned From Building Departments | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(1.5), EPE(1.5), MCPE(1.5), MI(1.5), RBO(1.5), RPE(1.5), RBI(1.5), RMI(1.5) |
| BBS2017-530 | BrewDog Brewery & Franklin Park Conservatory Tour | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(5.0), BO(5.0), FPI(5.0), LPE(5.0), MI(5.0), RBI(5.0), RBO(5.0), REPE(5.0), RMI(5.0), RPE(5.0), RPI(5.0) |
| BBS2017-529 | Bridge Park Project Tour | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-274 | Code Official Institute | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(22.0), BO(22.0), FPI(22.0), MPE(22.0), MI(22.0), RBI(22.0), RBO(22.0), RPE(22.0), RPI(22.0) |
| BBS2017-519 | Construction Code & Construction Innovation-Intersection of Progress | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(1.5), MPE(1.5), BI(1.5), RBO(1.5), RPE(1.5), RBI(1.5) |
| BBS2017-546 | Disaster Experiences Gained | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), RBI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-513 | Disasters & the Disaster Response Inspector | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), FPI(1.5), MI(1.5), NRIUI(1.5), PI(1.5), RBI(1.5), RBO(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5), MPE(1.5) |
| BBS2017-523 | Duct Inspection From Construction to Leakage Testing | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(3.0), BI(3.0), RBO(3.0), RBI(3.0) |
| BBS2017-482 | Enhance Your Career: How to Get Involved With an ICC Committee | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|-----|--------------|----------------|---------------------|---|
| BBS2017-512 | Ethics in Code Administration | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5) |
| BBS2017-349 | Fire & Life Safety Institute | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(18.0), BO(18.0), EPE(18.0), FPI(18.0), MPE(18.0), MI(18.0), PI(18.0), PPE(18.0), MCPE(18.0) |
| BBS2017-525 | Fire Code Fundamentals | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), FPI(1.5), RBO(1.5), RBI(1.5) |
| BBS2017-516 | Firestopping: Plan Review & Inspection of Joints | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MCPE(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-508 | Going Paperless & Digital | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), ESI(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5) |
| BBS2017-515 | High-Piles Combustible Storage | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(3.0), FPI(3.0), RBO(3.0) |
| BBS2017-507 | How to "Handle" the Media | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-547 | HUD's Model Installation Standards for Manufactured Homes | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), RBI(1.5), RBO(1.5), RPE(1.5) |
| BBS2017-148 | Inspector Skills | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(6.0), BO(6.0), ESI(6.0), FPI(6.0), MI(6.0), NRIUI(6.0), PI(6.0), RBI(6.0), RBO(6.0), RIUI(6.0), RMI(6.0) |
| BBS2017-386 | Leadership Institute | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(18.0), MCPE(18.0), PPE(18.0), EPE(18.0), MPE(18.0), BI(18.0), FPI(18.0), MI(18.0), PI(18.0), RBO(18.0), RPE(18.0), RBI(18.0), RMI(18.0) |
| BBS2017-522 | Ohio Building Code Update | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), MI(3.0), PI(3.0), RBI(3.0), RBO(3.0), RPI(3.0) |
| BBS2017-526 | Ohio State University Stadium & Woody Hayes Athletic Center | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RPI(3.0) |
| BBS2017-527 | Palace Theatre & Lincoln LeVeque Building Tour | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RPE(3.0), RPI(3.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|-----|--------------|----------------|---------------------|---|
| BBS2017-272 | Permit Technician Institute | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(6.0) |
| BBS2017-385 | Principles of Building Safety Institute | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(12.0), MCPE(12.0), PPE(12.0), EPE(12.0), BI(12.0), MPE(12.0), FPI(12.0), MI(12.0), PI(12.0), RBO(12.0), RPE(12.0), RBI(12.0), RMI(12.0) |
| BBS2017-186 | Report Writing for Code Inspectors | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(6.0), BO(6.0), EPE(6.0), ESI(6.0), FPI(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0) |
| BBS2017-384 | Residential Building Inspection Certification Academy | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | RBO(21.0), RBI(21.0), RPE(21.0) |
| BBS2017-455 | Residential Inspection Institute (2015 I-Codes) (based on the 2015 I-Codes) (5days) | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(30.0), BO(30.0), EPE(30.0), LPE(30.0), MPE(30.0), MI(30.0), MCPE(30.0), PI(30.0), PPE(30.0), RBI(30.0), RBO(30.0), REPE(30.0), RMI(30.0), RPE(30.0), RPI(30.0) |
| BBS2017-456 | S1-Structural Steel & Bolting Special Inspector Certification Test Academy (2.5 days) | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(15.0), BI(15.0) |
| BBS2017-528 | Smith Brothers Hardware Company Tour | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-548 | Social Media – A Tool in Promoting Code Officials | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(1.5), RBO(1.5) |
| BBS2017-484 | Special Inspections – Implementing & Managing IBC Chapter 17, Requirements For Building Departments | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(1.5), BI(1.5), RBO(1.5), RBI(1.5) |
| BBS2017-517 | Sticky Points | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(3.0), BO(3.0), EPE(3.0), LPE(3.0), MPE(3.0), MCPE(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RPE(3.0), RPI(3.0), FPI(3.0), MI(3.0), PI(3.0), RMI(3.0), RIUI(3.0) |
| BBS2017-514 | The Future of Hazard Resilience: Building Codes & Best Practices | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5) |
| BBS2017-510 | The Generational Divide in the Public Sector | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5) |
| BBS2017-520 | The Top 10 Approach to Commercial Energy Code Compliance | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BO(3.0), BI(3.0), RBO(3.0), RBI(3.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|--------------------------------------|-----------------|----------------|------------------------|---|
| BBS2017-518 | Vacancy, Blight & Local Governments | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), LPE(1.5), MPE(1.5), MCPE(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RPE(1.5), RPI(1.5) |
| BBS2017-545 | What to Look for When Conduction Plan Reviews& Inspections of Solar PV | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(1.5), BO(1.5), EPE(1.5), ESI(1.5), MPE(1.5), RBI(1.5), RBO(1.5), RPE(1.5) |
| BBS2017-273 | When Disaster Strikes Institute | ICC | Laura Garcia | (888) 422-7233 | lmorris@iccsafe.org | BI(12.0), BO(12.0), MPE(12.0), RBI(12.0), RBO(12.0), RPE(12.0) |
| BBS2017-445 | 2009 IECC Overview – Residential | ICF - Columbia Gas | Rick Gazica | (412) 446-4696 | rick.gazica@icf.com | BO(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-506 | 2017 Code Changes | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), ESI(3.0) |
| BBS2017-485 | Common Code Violations - Electrical | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), ESI(3.0), RBO(3.0), RPE(3.0), RBI(3.0) |
| BBS2017-505 | Fire Alarm Systems & Fire Pumps | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), FPI(3.0), ESI(3.0) |
| BBS2017-003 | Low Voltage Systems | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | EPE(3.0), BI(3.0), ESI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), BO(3.0), MPE(3.0) |
| BBS2017-002 | Renewable Energies | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), ESI(3.0), RBO(3.0), RPE(3.0), RBI(3.0) |
| BBS2017-004 | Separately Derived Systems | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), ESI(3.0), RBO(3.0), RPE(3.0), RBI(3.0) |
| BBS2017-001 | Services | IEC of Greater Cincinnati | Kevin Collins | (513) 542-0400 | kcollins@iec-cincy.com | BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), ESI(3.0), RBO(3.0), RPE(3.0), RBI(3.0) |
| BBS2017-061 | 2013 RCO Chapter 113 Existing Buildings | Institute For Professional Education | Paul Fussner | (216) 299-9367 | pfussner.ipe@att.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-062 | 2014 NEC Article 250 | Institute For Professional Education | Paul Fussner | (216) 299-9367 | pfussner.ipe@att.net | BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RPE(8.0), RBO(8.0) |
| BBS2017-064 | 2014 NEC Articles 230 - 450 | Institute For Professional Education | Paul Fussner | (216) 299-9367 | pfussner.ipe@att.net | MPE(4.0), RPE(4.0), RBO(4.0), BO(4.0), EPE(4.0), ESI(4.0) |
| BBS2017-063 | 2014 NEC Articles 90 - 225 | Institute For Professional Education | Paul Fussner | (216) 299-9367 | pfussner.ipe@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-065 | 30 Hour Home Study Course (NEC 2014) | Institute For Professional Education | Paul Fussner | (216) 299-9367 | pfussner.ipe@att.net | BO(30.0), EPE(30.0), ESI(30.0), MPE(30.0), RBO(30.0), RPE(30.0) |
| BBS2017-346 | Maintaining The Integrity of Fire Rated Construction | INTEK Construction Products Inc | Jeffery Molchan | (216) 398-3300 | j.molchan@intekcp.com | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-347 | Maintaining The Integrity of Fire Rated Construction | INTEK Construction Products Inc | Jeffery Molchan | (216) 398-3300 | j.molchan@intekcp.com | BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), FPI(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0) |
| BBS2017-371 | Flashing & Water Penetration | Int'l Masonry Institute | Tom Elliott | (440) 986-2260 | telliott@imiweb.org | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|-----------------------------------|------------------|----------------|----------------------------|---|
| BBS2017-373 | Grouting & Reinforced Masonry Construction | Int'l Masonry Institute | Tom Elliott | (440) 986-2260 | telliott@imiweb.org | BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-370 | Masonry Movement Joints | Int'l Masonry Institute | Tom Elliott | (440) 986-2260 | telliott@imiweb.org | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-372 | Understanding Masonry Tolerances | Int'l Masonry Institute | Tom Elliott | (440) 986-2260 | telliott@imiweb.org | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-187 | 2017 NEC Changes (online course) | JADE Learning LLC | Amy Bonilla | (919) 781-4477 | ahbonilla@jadelearning.com | ESI(16.0) |
| BBS2017-498 | Commercial & Industrial Wiring (2017 NEC) (online) | JADE Learning LLC | Amy Bonilla | (919) 781-4477 | ahbonilla@jadelearning.com | ESI(8.0) |
| BBS2017-497 | Residential Wiring (2017 NEC) (online) | JADE Learning LLC | Amy Bonilla | (919) 781-4477 | ahbonilla@jadelearning.com | ESI(8.0) |
| BBS2017-332 | Understanding Mass Notification Systems Planning / Risk / Design (Campus Fire Safety Conference) | Jensen Hughes Inc | Timothy LaRose | (410) 737-8677 | contact@jensenhughes.com | BI(1.0), BO(1.0), EPE(1.0), FPI(1.0), MPE(1.0) |
| BBS2017-340 | 2014 NEC Changes & Updates (Course 1 – Articles 100-230) | John M Labriola | John Labriola | (330) 497-6309 | summitcbo@yahoo.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-341 | 2014 NEC Changes & Updates (Course 2 – Articles 240-334) | John M Labriola | John Labriola | (330) 497-6309 | summitcbo@yahoo.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-342 | 2014 NEC Changes & Updates (Course 3 – Articles 338-516) | John M Labriola | John Labriola | (330) 497-6309 | summitcbo@yahoo.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-343 | 2014 NEC Changes & Updates (Course 4 – Article 517) | John M Labriola | John Labriola | (330) 497-6309 | summitcbo@yahoo.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-344 | 2014 NEC Changes & Updates (Course 5 – Articles 590-690) | John M Labriola | John Labriola | (330) 497-6309 | summitcbo@yahoo.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-345 | 2014 NEC Changes & Updates (Course 6 – Articles 694-800) | John M Labriola | John Labriola | (330) 497-6309 | summitcbo@yahoo.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-398 | Authority Having Jurisdiction (AHJ) Seminar | Koorsen Fire & Security | Bradley Howard | (614) 853-5673 | brad.howard@koorsen.com | BO(6.0), MPE(6.0), BI(6.0), FPI(6.0), MI(6.0) |
| BBS2017-161 | Energy Compliance in the Residential Code of Ohio Systems with Fire Alarm Systems (Joint Conference) | Licking County Building Code Dept | Troy Warnock | | | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0) |
| BBS2017-323 | Significant Changes to the 2017 NEC | Mansfield Area Electrical JATC | William Thompson | (419) 526-4688 | wthompson@ibew688.org | BI(8.0), BO(8.0), ESI(8.0), MPE(8.0), RBI(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-138 | Fire Door Systems, A Guide To Code Compliance | McKeon Door Co | David Dodge | (801) 471-7210 | ddodge@mckeondoors.com | BO(5.0), MPE(5.0), BI(5.0), FPI(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-325 | 2017 Analysis of the NEC Code Changes (Chapters 1-4) | MECA | Steve Glaser | (937) 264-0418 | laurameca@aol.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-326 | 2017 Analysis of the NEC Code Changes (Chapters 5-9) | MECA | Steve Glaser | (937) 264-0418 | laurameca@aol.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-354 | Round Table Discussion: Electronic Plan Review | MVBOC - Pete Baldauf | Pete Baldauf | (937) 415-2326 | esi@vandaliaohio.org | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|-------------------------|--------------|----------------|--------------------------|--|
| BBS2017-355 | Round Table Discussion: OBC Chapter 10- Means of Egress | MVBOC - Pete Baldauf | Pete Baldauf | (937) 415-2326 | esi@vandaliaohio.org | BI(1.0), BO(1.0), EPE(1.0), FPI(1.0), MPE(1.0), MCPE(1.0), NRIUI(1.0) |
| BBS2017-356 | Round Table Discussion: OBC Chapter 27 & RCO, Chapter 34 | MVBOC - Pete Baldauf | Pete Baldauf | (937) 415-2326 | esi@vandaliaohio.org | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-353 | Round Table Discussion: Smoke Alarms / Carbon Monoxide Detectors | MVBOC - Pete Baldauf | Pete Baldauf | (937) 415-2326 | esi@vandaliaohio.org | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-396 | Understanding the UL Fire Resistance Directory & Various Assemblies (outside of conference) | National Gypsum Company | Thad Goodman | (614) 296-5375 | thadg@nationalgypsum.com | BI(1.0), BO(1.0), FPI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0) |
| BBS2017-182 | Understanding the UL Fire Resistant Directory & Various Assemblies (Joint Conference) | National Gypsum Company | Thad Goodman | (614) 296-5375 | thadg@nationalgypsum.com | BI(1.0), BO(1.0), FPI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), PPE(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RBI(1.0), RMI(1.0), RIUI(1.0) |
| BBS2017-193 | Monthly Building Code Meeting & Update (Apr 5) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-197 | Monthly Building Code Meeting & Update (Aug 2) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-201 | Monthly Building Code Meeting & Update (Dec 6) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-191 | Monthly Building Code Meeting & Update (Feb 1) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-190 | Monthly Building Code Meeting & Update (Jan 4) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-196 | Monthly Building Code Meeting & Update (Jul 5) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-195 | Monthly Building Code Meeting & Update (Jun 7) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-192 | Monthly Building Code Meeting & Update (Mar 1) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-194 | Monthly Building Code Meeting & Update (May 3) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-200 | Monthly Building Code Meeting & Update (Nov 1) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-199 | Monthly Building Code Meeting & Update (Oct 4) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-198 | Monthly Building Code Meeting & Update (Sep 6) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-205 | Monthly Electrical Code Meeting & Update (Apr 12) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-209 | Monthly Electrical Code Meeting & Update (Aug 9) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|---|----------------|----------------|----------------------|--|
| BBS2017-213 | Monthly Electrical Code Meeting & Update (Dec 13) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-203 | Monthly Electrical Code Meeting & Update (Feb 8) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-202 | Monthly Electrical Code Meeting & Update (Jan 11) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-208 | Monthly Electrical Code Meeting & Update (Jul 12) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-207 | Monthly Electrical Code Meeting & Update (Jun 14) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-204 | Monthly Electrical Code Meeting & Update (Mar 8) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-206 | Monthly Electrical Code Meeting & Update (May10) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-212 | Monthly Electrical Code Meeting & Update (Nov 8) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-211 | Monthly Electrical Code Meeting & Update (Oct 11) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-210 | Monthly Electrical Code Meeting & Update (Sep 13) | National Inspection | Scott Young | (937) 433-4642 | plans@natinspect.com | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-501 | National Electrical Code 2017 Update | NE Ohio Regional Sewer District (NEORS) | David Nemchik | (216) 641-3200 | nemchikd@neorsd.org | BO(3.5), MPE(3.5), EPE(3.5), ESI(3.5), RBO(3.5), RPE(3.5) |
| BBS2017-550 | 2017 NEC (3-day course) | NFPA | Leah Aleixo | (508) 895-8365 | laleixo@nfpa.org | BI(21.0), BO(21.0), EPE(21.0), ESI(21.0), MPE(21.0) |
| BBS2017-336 | NFPA 25 – 2014 Update & Significant Change(Campus Fire Safety Conference) | NFSA (Jason Webb) | Jason Webb | (845) 878-4200 | webb@nfsa.org | BI(1.0), BO(1.0), FPI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0) |
| BBS2017-328 | Coordinating NFPA 25 & 72 Inspecting, Testing & Maintenance Requirements | NFSA (Ron Ritchey) | Ron Ritchey | (765) 412-6707 | ritchey@nfsa.org | MPE(8.0), BI(8.0), FPI(8.0) |
| BBS2017-270 | Fire Service Mains & Their Appurtenances (Underground Piping) | NFSA (Ron Ritchey) | Ron Ritchey | (765) 412-6707 | ritchey@nfsa.org | BO(7.0), MPE(7.0), BI(7.0), FPI(7.0) |
| BBS2017-503 | Navigating the Storage Requirements in NFPA 13 | NFSA (Ron Ritchey) | Ron Ritchey | (765) 412-6707 | ritchey@nfsa.org | FPI(7.0) |
| BBS2017-329 | NFPA 13 – Sprinkler System Installation Requirements | NFSA (Ron Ritchey) | Ron Ritchey | (765) 412-6707 | ritchey@nfsa.org | BI(7.0), FPI(7.0) |
| BBS2017-533 | Understanding, Applying, & Enforcing NFPA 25 | NFSA (Ron Ritchey) | Ron Ritchey | (765) 412-6707 | ritchey@nfsa.org | BO(7.0), BI(7.0), FPI(7.0) |
| BBS2017-158 | Building Science for Building Officials | Nu Wool Co | Robert DeVries | (616) 669-0100 | rdevries@nuwool.com | BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0) |
| BBS2017-084 | Cellulose Insulation | Nu Wool Co | Robert DeVries | (616) 669-0100 | rdevries@nuwool.com | BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0) |
| BBS2017-083 | Understanding the 2009 IECC | Nu Wool Co | Robert DeVries | (616) 669-0100 | rdevries@nuwool.com | BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|------------------------------|---------------------|----------------|----------------------------|---|
| BBS2017-162 | 2017 OAPI Conference Courses (Day 1) | OAPI (James A Richardson Jr) | James Richardson Jr | (614) 645-6340 | jarichardson@columbus.gov | MI(2.0), BI(2.0), BO(2.0), MPE(2.0), MCPE(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RMI(2.0), RPE(2.0) |
| BBS2017-163 | 2017 OAPI Conference Courses (Day 2 & 3) | OAPI (James A Richardson Jr) | James Richardson Jr | (614) 645-6340 | jarichardson@columbus.gov | BI(10.0), BO(10.0), MPE(10.0), MI(10.0), MCPE(10.0), PI(10.0), PPE(10.0), RBI(10.0), RBO(10.0), REPE(10.0), RMI(10.0), RPE(10.0) |
| BBS2017-164 | 2017 OAPI Conference Courses (Day 4) | OAPI (James A Richardson Jr) | James Richardson Jr | (614) 645-6340 | jarichardson@columbus.gov | BI(3.0), BO(3.0), MPE(3.0), MI(3.0), MCPE(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RMI(3.0), RPE(3.0) |
| BBS2017-234 | OPC Chater 9 - Venting Methods (Joint Conference) | OBOA (James A Richardson Jr) | James Richardson Jr | (614) 645-6340 | jarichardson@columbus.gov | MPE(2.0), MCPE(2.0), BI(2.0), BO(2.0), PPE(2.0), MI(2.0), PI(2.0), NRIUI(2.0), RBO(2.0), RPE(2.0), RBI(2.0), RIUI(2.0) |
| BBS2017-185 | Temporary Door Locking Devices in School Buildings (Joint Conference) | OBOA (Mike Rudey) | Mike Rudey | (419) 354-9190 | mrudey@co.wood.oh.us | BI(1.0), BO(1.0), EPE(1.0), FPI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), PPE(1.0), PI(1.0) |
| BBS2017-357 | Analysis of Changes Chap. 1& 2 (2017 NEC) Course 1 | OCIB - Mary Ward | Mary Ward | (740) 591-5448 | rlw8169@yahoo.com | ESI(2.0) |
| BBS2017-358 | Analysis of Changes Chap. 3 (2017 NEC) Course 2 | OCIB - Mary Ward | Mary Ward | (740) 591-5448 | rlw8169@yahoo.com | ESI(2.0) |
| BBS2017-359 | Analysis of Changes Chap. 4 (2017 NEC) Course 3 | OCIB - Mary Ward | Mary Ward | (740) 591-5448 | rlw8169@yahoo.com | ESI(2.0) |
| BBS2017-360 | Analysis of Changes Chap. 5&6 (2017 NEC) Course 4 | OCIB - Mary Ward | Mary Ward | (740) 591-5448 | rlw8169@yahoo.com | ESI(2.0) |
| BBS2017-361 | Analysis of Changes Chap. 7& 8 (2017 NEC) Course 5 | OCIB - Mary Ward | Mary Ward | (740) 591-5448 | rlw8169@yahoo.com | ESI(2.0) |
| BBS2017-362 | Analysis of Changes Chap. 7& 8 (2017 NEC) Courses 1-5 | OCIB - Mary Ward | Mary Ward | (740) 591-5448 | rlw8169@yahoo.com | ESI(9.0) |
| BBS2017-124 | OCILB Updates | OCILB | Carol Ross | (614) 644-3494 | carol.ross@com.state.oh.us | BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0) |
| BBS2017-535 | 2017 Ohio Statewide Floodplain Management Conference | OFMA | Stephen Moore | (614) 830-2045 | smoore@groveport.org | BI(8.0), BO(8.0), EPE(8.0), LPE(8.0), MPE(8.0), MI(8.0), MCPE(8.0), PI(8.0), PPE(8.0), RBI(8.0), RBO(8.0), REPE(8.0), RMI(8.0), RPE(8.0), RPI(8.0) |
| BBS2017-299 | 2017 NEC Changes | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-300 | 2017 NEC Changes | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-301 | 2017 NEC Changes | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-240 | Health Care Facilities (basic) | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|--------------------------|--------------|----------------|--------------------|---|
| BBS2017-241 | Health Care Facilities (extended) | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-232 | Health Care Facilities Basic (Joint Conference) | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), MPE(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-233 | Health Care Facilities Extended (Joint Conference) | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), MPE(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-488 | How to Use the NEC | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), MPE(4.0), EPE(4.0), RBO(4.0), RPE(4.0), RBI(4.0) |
| BBS2017-490 | How to Use the NEC & Grounding & Bonding Services | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), MPE(8.0), EPE(8.0), RBO(8.0), RPE(8.0), RBI(8.0) |
| BBS2017-489 | How to Use the NEC & Healthcare Facilities | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), MPE(8.0), EPE(8.0), RBO(8.0), RMI(8.0), RBI(8.0) |
| BBS2017-491 | How to Use the NEC & Motors | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), MPE(8.0), EPE(8.0), RBO(8.0), RPE(8.0), RBI(8.0) |
| BBS2017-255 | Motors & Motor Circuits | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-247 | P. V. Systems | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | RPE(2.0), BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0) |
| BBS2017-248 | P. V. Systems | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-256 | PV Systems & Health Care Facilities | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-245 | Residential Wiring | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-246 | Residential Wiring & NEC Calculations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-252 | Soares Grounding & Bonding /Services | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-253 | Soares Grounding & Bonding /Services | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-254 | Soares Grounding & Bonding /Services | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-249 | Soares Grounding /Separately Derived Systems for Special Locations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-250 | Soares Grounding /Separately Derived Systems for Special Locations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |
| BBS2017-251 | Soares Grounding /Separately Derived Systems for Special Locations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), EPE(8.0), ESI(8.0), RBO(8.0), RPE(8.0), MPE(8.0) |
| BBS2017-242 | Understanding NEC Calculations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-243 | Understanding NEC Calculations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|--|--------------------------------|------------------|----------------|------------------------------------|---|
| BBS2017-244 | Understanding NEC Calculations | Ohio Certificate Renewal | Harold Plant | (614) 519-1698 | harold2112@att.net | BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-330 | 2017 NEC Code Changes 1.1 (Art. 100-250) | Ohio Electrical Training | Joseph Ponzio | (614) 581-5700 | oh.electrical.training@gmail.com | BO(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0) |
| BBS2017-125 | The Ohio Ethics Law (Joint Conference Only) | Ohio Ethics Commission | Susan Willeke | (614) 466-7090 | susan.willeke@ethics.state.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-126 | The Ohio Ethics Law (other than conference) | Ohio Ethics Commission | Susan Willeke | (614) 466-7090 | susan.willeke@ethics.state.oh.us | BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0) |
| BBS2017-258 | Cold Weather Concrete Construction | Ohio Ready Mixed Concrete Assn | Thomas Rozsits | (614) 891-0210 | tom@ohioconcrete.org | BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0) |
| BBS2017-327 | Introduction to Ventilation (Joint Conference) | Panasonic Eco Solutions | Jeff Klonowski | (920) 737-2758 | jeffery.klonowski@us.panasonic.com | BI(1.0), BO(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0) |
| BBS2017-291 | 2017 NEC Changes /IAEI Analysis / Mike Holt (Part 1) (Articles 400 -490) | Robert O'Connors | Robert O'Connors | (937) 644-2521 | boconno@live.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-292 | 2017 NEC Changes /IAEI Analysis / Mike Holt (Part 2) (Articles 501-590) | Robert O'Connors | Robert O'Connors | (937) 644-2521 | boconno@live.com | BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0) |
| BBS2017-159 | Changes in 2017 NEC | Ron Tusing & Associates | Ron Tusing | (419) 668-7688 | ron@rontusing.com | ESI(10.0) |
| BBS2017-543 | 2015 International Mechanical Plan Review (5-day course) | Safebuilt | Tinika Blackmon | (404) 695-4261 | tblackmon@safebuilt.com | BI(40.0), BO(40.0), EPE(40.0), MPE(40.0), MCPE(40.0), PPE(40.0), RBI(40.0), RBO(40.0), RPE(40.0) |
| BBS2017-544 | 2015 International Plumbing Plan Review (4-day course) | Safebuilt | Tinika Blackmon | (404) 695-4261 | tblackmon@safebuilt.com | BI(32.0), BO(32.0), EPE(32.0), MPE(32.0), MCPE(32.0), PPE(32.0), RBI(32.0), RBO(32.0), RPE(32.0) |
| BBS2017-502 | Getting the Code Official & Special Event Partners Under the Same Tent | SAFTSE Inc | Jim Erickson | (715) 559-1864 | jim@saftse.org | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-170 | Elevator Inspections from a Manufacturer's Perspective (Joint Conference Only) | Schindler Elevator | Norman Martin | (216) 882-4926 | norman.martin@us.schindler.com | BI(1.0), BO(1.0), EPE(1.0), MPE(1.0), MCPE(1.0), FPI(1.0), MI(1.0) |
| BBS2017-214 | Cold Formed Steel & Curtain Wall Connections | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BO(1.0), MPE(1.0), BI(1.0) |
| BBS2017-219 | Continuous Load Path: Beyond the Basics of Wood Framing | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-220 | Continuous Load Path: Beyond the Basics of Wood Framing | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(2.0), BO(2.0), MPE(2.0), RBO(2.0), RPE(2.0), RBI(2.0) |
| BBS2017-221 | Continuous Load Path: Beyond the Basics of Wood Framing | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(3.0), BO(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-222 | Continuous Load Path: Beyond the Basics of Wood Framing | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(6.0), BO(6.0), MPE(6.0), RBI(6.0), RBO(6.0), RPE(6.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|------------------------------------|---------------------|----------------|-----------------------------|---|
| BBS2017-215 | Deck, Porch, Balcony Framing Connection Seminar | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-216 | Deck, Porch, Balcony Framing Connection Seminar | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0) |
| BBS2017-217 | Deck, Porch, Balcony Framing Connection Seminar | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(3.0), BO(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0) |
| BBS2017-218 | Deck, Porch, Balcony Framing Connection Seminar | Simpson Strong-Tie | Greg Wujcik | (614) 850-4125 | gwujcik@strongtie.com | BI(6.0), BO(6.0), MPE(6.0), RBI(6.0), RBO(6.0), RPE(6.0) |
| BBS2017-486 | Deck Building 101 – Beginner’s Course (online) | Simpson Strong-tie (Ian McCallion) | Ian McCallion | (925) 560-2631 | imccallion@strongtie.com | BO(1.0), MPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-289 | How to Identify Code Compliant Anchor Designs | Simpson Strong-tie (Ian McCallion) | Ian McCallion | (925) 560-2631 | imccallion@strongtie.com | BI(1.0), BO(1.0), MPE(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-290 | Improving the Performance of Wood-Framed Structures in a Tornado | Simpson Strong-tie (Ian McCallion) | Ian McCallion | (925) 560-2631 | imccallion@strongtie.com | BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0) |
| BBS2017-239 | CPVC Wet Sprinkler Systems for NFPA 13, 13R, & 13D | Spears Manufacturing Co | Thomas Rauenswinder | (614) 946-9897 | trauenswinder@spearsmfg.net | BI(3.0), BO(3.0), FPI(3.0), MPE(3.0), MI(3.0), RBI(3.0), RBO(3.0), RPE(3.0), PPE(3.0) |
| BBS2017-453 | Basic Overview of Provisions For Exterior Wall Assemblies & Wall Coverings in OBC & RCO | State of Ohio, Commerce, DIC | Yeong-Tarng Jiang | (614) 644-3492 | ytjiang@com.state.oh.us | BO(3.0), MPE(3.0), BI(3.0), RBO(3.0), RPE(3.0), RBI(3.0) |
| BBS2017-171 | Basic Overview of Structural Provisions in OBC | State of Ohio, Commerce, DIC | Yeong-Tarng Jiang | (614) 644-3492 | ytjiang@com.state.oh.us | BO(4.0), MPE(4.0), BI(4.0) |
| BBS2017-169 | Ohio Elevator Review (Joint Conference Only) | State of Ohio, DIC, Elevators | Chip Updyke | (513) 509-4831 | cupdyke@com.state.oh.us | BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0) |
| BBS2017-160 | Changes in 2017 NEC Systems with Fire Alarm Systems | Swanson, John | John Swanson | (952) 261-5854 | john_r_swanson@hotmail.com | BO(3.5), MPE(3.5), BI(3.5), FPI(3.5), RBO(3.5), RPE(3.5) |
| BBS2017-331 | Temporary Door Locking Devices | The Preview Group Inc | Sarah Rice | (513) 621-2109 | srice@preview-group.com | BO(1.5), MPE(1.5), BI(1.5), FPI(1.5) |
| BBS2017-165 | Practical 2017 NEC Training (Day 1) | Timothy Pool LLC | Timothy Pool | (440) 497-0060 | timpool@sbcglobal.net | BO(2.5), MPE(2.5), EPE(2.5), ESI(2.5) |
| BBS2017-166 | Practical 2017 NEC Training (Day 2) | Timothy Pool LLC | Timothy Pool | (440) 497-0060 | timpool@sbcglobal.net | BO(2.5), MPE(2.5), EPE(2.5), ESI(2.5) |
| BBS2017-167 | Practical 2017 NEC Training (Day 3) | Timothy Pool LLC | Timothy Pool | (440) 497-0060 | timpool@sbcglobal.net | BO(2.5), MPE(2.5), EPE(2.5), ESI(2.5) |
| BBS2017-168 | Practical 2017 NEC Training (Day 4) | Timothy Pool LLC | Timothy Pool | (440) 497-0060 | timpool@sbcglobal.net | BO(2.5), MPE(2.5), EPE(2.5), ESI(2.5) |
| BBS2017-011 | Electrical Safety Inspector Training & Update Course (2014 NEC – Chap. 1 & 2) (Day 1) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), RBO(5.0), RBI(5.0), ESI(5.0) |
| BBS2017-013 | Electrical Safety Inspector Training & Update Course (2014 NEC – Chap. 2 & 3) (Day 3) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), RBO(5.0), RBI(5.0), ESI(5.0) |
| BBS2017-012 | Electrical Safety Inspector Training & Update Course (2014 NEC – Chap. 2) (Day 2) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), RBO(5.0), RBI(5.0), ESI(5.0) |
| BBS2017-014 | Electrical Safety Inspector Training & Update Course (2014 NEC – Chap. 3 & 4) (Day 4) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), RBO(5.0), RBI(5.0), ESI(5.0) |
| BBS2017-015 | Electrical Safety Inspector Training & Update Course (2014 NEC – Chap. 4) (Day 5) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), RBO(5.0), RBI(5.0), ESI(5.0) |

2017 BBS Course Listing
(by Sponsor)

| | | | | | | |
|-------------|---|---|-------------------|----------------|---------------------------------|--|
| BBS2017-016 | Electrical Safety Inspector Training & Update Course (2014 NEC – Chap. 8) (Day 6) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | BO(5.0), MPE(5.0), EPE(5.0), BI(5.0), RBO(5.0), RBI(5.0), ESI(5.0) |
| BBS2017-005 | Plumbing Code & Code Updates (Chap. 13 – Referenced Standards) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | PPE(5.0), PI(5.0), RPI(5.0) |
| BBS2017-006 | Plumbing Code & Code Updates (Chap. 2 – Certification of Building Department Personnel) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | PPE(5.0), PI(5.0), RPI(5.0) |
| BBS2017-010 | Plumbing Code & Code Updates (Chap. 2 – Plumbing Definitions) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | PPE(5.0), PI(5.0), RPI(5.0) |
| BBS2017-007 | Plumbing Code & Code Updates (Chap. 3 – Building Permits & Plan Approval) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | PPE(5.0), PI(5.0), RPI(5.0) |
| BBS2017-008 | Plumbing Code & Code Updates (Chap. 4 – Inspection & Testing – Certificate of Occupancy) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | PPE(5.0), PI(5.0), RPI(5.0) |
| BBS2017-009 | Plumbing Code & Code Updates (Chap. 5 – Violations – Stop Work Order Unsafe Building Products & Material) | Training Agency 253 | Howard Sonenstein | (440) 442-6613 | howardsonenstein@aol.com | PPE(5.0), PI(5.0), RPI(5.0) |
| BBS2017-236 | Fire Resistive Construction | UL LLC (Richard Walke) | Richard Walke | (847) 664-3084 | richard.n.walke@ul.com | BI(3.0), BO(3.0), ESI(3.0), FPI(3.0), MPE(3.0), MI(3.0) |
| BBS2017-235 | Fire Resistive Construction (Joint Conference Only) | UL LLC (Richard Walke) | Richard Walke | (847) 664-3084 | richard.n.walke@ul.com | BI(2.0), BO(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0) |
| BBS2017-333 | Understanding the UL Monitoring Systems Certification Program (Campus Fire Safety Conference) | UL LLC / Underwriters Labs (Thomas Presnak) | Thomas Presnak | (847) 778-1109 | thomas.e.presnak@ul.com | BO(1.0), MPE(1.0), BI(1.0), FPI(1.0) |
| BBS2017-130 | Dry Sprinklers | Victaulic | Cynthia Nunez | (610) 923-3900 | cnunez@victaulic.com | BI(1.0), BO(1.0), FPI(1.0), MPE(1.0), MI(1.0), PI(1.0), PPE(1.0) |
| BBS2017-131 | Pressure Regulating Devices in Commercial Fire Protection | Victaulic | Cynthia Nunez | (610) 923-3900 | cnunez@victaulic.com | BI(2.0), BO(2.0), FPI(2.0), MPE(2.0), PPE(2.0), MI(2.0), PI(2.0) |
| BBS2017-263 | Framing Floor Systems With Engineered Wood Products | Weyerhaeuser | Jason Shumaker | (888) 453-8358 | jason.shumaker@weyerhaeuser.com | BO(1.0), MPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-262 | RCO 502.14 Fire Resistance of Floor & Equivalent Protection Options | Weyerhaeuser | Jason Shumaker | (888) 453-8358 | jason.shumaker@weyerhaeuser.com | BO(1.0), MPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-261 | Tall Wall Seminar | Weyerhaeuser | Jason Shumaker | (888) 453-8358 | jason.shumaker@weyerhaeuser.com | BO(1.0), MPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0) |
| BBS2017-155 | 2017 Analysis of Changes, Part 1 | Winkelectric | Clifford Winker | (440) 346-4125 | winkelectric@hotmail.com | MPE(5.0), EPE(5.0), ESI(5.0) |
| BBS2017-156 | 2017 Analysis of Changes, Part 2 | Winkelectric | Clifford Winker | (440) 346-4125 | winkelectric@hotmail.com | MPE(5.0), EPE(5.0), ESI(5.0) |