

**Known Errata in the 2011 Ohio Building Codes** (April 2012)

The Board of Building Standards (BBS) staff, after filing the official rules that make up the Ohio building codes, occasionally finds errors in the rules and/or the publishers' copies of the codes. These known errors are listed in the following table for your reference. These errata require a BBS rule change and will be included in an upcoming public hearing tentatively scheduled for the fall of 2012.

Please contact a BBS technical staff member at (614)644-2613 if you discover an error in any of the Ohio codes that are not shown on this list.

<b>Ohio Building Code (OBC)</b>		
<b>Code Section</b>	<b>Description of Error</b>	<b>Action required to correct error</b>
Chapter 2	Definition of ALARM NOTIFICATION APPLIANCE should reference Section 902.1.	Publishers need to make change
406.2.2	Reference should be to Chapter 11 and ICC A117.1 (not ADAAG)	BBS rule change
407.3.2, Exception	Reference should be to Section 1008.1.9.6 (not 1008.1.8.6.2)	BBS rule change
412.3.6	Reference should be to Chapter 11 and ICC A117.1 (not ADAAG)	BBS rule change
903.5	Reference should be to the <i>fire code</i> (not the International Fire Code)	BBS rule change
907.5.2	References should be to Chapter 11, ICC A117.1, and NFPA 72 (not ADAAG)	BBS rule change
907.5.2.2	Second sentence reference should be to Section 404 of the <i>fire code</i> (not to OBC Section 404 and not to the International Fire Code)	BBS rule change
1012.6	The second sentence should end with the word "riser".	BBS rule change
Table 1016.1	Add the following under footnote "a": " <i>Section 1016.3: For increased limitation in Groups F-1 and S-1.</i> "	BBS rule change
1016.3	Add section 1016.3 that reads as follows: " <b>1016.3 Group F-1 and S-1 increase.</b> <i>The maximum exit access travel distance shall be 400 feet (121,920 mm) in Group F-1 and S-1 occupancies where all of the following are met:</i> <ol style="list-style-type: none"> <li>1. <i>The portion of the building classified as Group F-1 or S-1 is limited to one story in height; and</i></li> <li>2. <i>The minimum height from the finished floor to</i></li> </ol>	BBS rule change

	<p><i>the bottom of the ceiling or roof slab or deck is 24 feet (7315 mm); and</i></p> <p>3. <i>The portion of the building classified as Group F-1 or S-1 is equipped throughout with an early suppression fast response (ESFR) automatic fire sprinkler system in accordance with Section 903.3.1.1; and</i></p> <p>4. <i>The portion of the building classified as Group F-1 or S-1 is equipped with a manually activated smoke exhaust system complying with Section 910.5”</i></p>	
3008.11.5	Reference should be to Chapter 11 and ICC A117.1 (not ADAAG)	BBS rule change
3008.13.1	Reference should be to <i>the Ohio Elevator Code</i> , Chapter 11, ICC A117.1, and NFPA 72 (not ADAAG)	BBS rule change
3008.13.2	Reference should be to <i>the Ohio Elevator Code</i> , Chapter 11, ICC A117.1, and NFPA 72 (not ADAAG)	BBS rule change
3501.4	ICC reference to IFC-09 should be deleted (all references to a fire code should now be to the “ <i>fire code</i> ”)	BBS rule change
<b>Ohio Plumbing Code (OPC)</b>		
<b>Code Section</b>	<b>Description of Error</b>	<b>Action Required to Correct Error</b>
ICC publication 1003.4 and Exception	The phrase “and in hydraulic elevator pits” should be deleted. The exception should be deleted in its entirety.	ICC should correct error and publish corrected code text