

**Ohio Department of Commerce
Division of State Fire Marshal
Bureau of Underground Storage Tank Regulations**

**Petroleum Underground Storage Tank
2009 Annual Report**

This Underground Storage Tank (UST) annual report is being provided as required by the Federal Energy Act of 2005 "Public Records Provision" for the reporting period of October 1, 2008 through September 30, 2009.

Public Record Post Date: **TBA (BUSTR to provide date when available/published)**

Ohio UST Statistics and Information for the Reporting Period

Inspection period: October 1, 2008 through September 30, 2009

Number of facilities inspected: **4,647**

Percent of UST facilities inspected with release prevention (corrosion protection, spill and overfill) and release detection requirements: **65.0%**

Total number of UST facilities at the end of the reporting period: **7,883**

Total number of underground storage tanks at the end of the reporting period: **22,895**

Summary Information for Releases

Total new UST releases that took place during the reporting period: **85**

Release reporting period: October 1, 2008 through September 30, 2009

| Source | Cause | | | | | | | | | | | | | |
|-----------------------------|-------|----|----------|----|---------------------|-----|-----------|----|--------------------|-----|-------|-----|---------|------|
| | Spill | | Overfill | | Phys/Mech Damage | | Corrosion | | Install Problem | | Other | | Unknown | |
| | # | % | # | % | # | % | # | % | # | % | # | % | # | % |
| Tank | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 17 | 100% |
| Piping | 0 | 0% | 0 | 0% | 5 | 17% | 1 | 3% | 4 | 13% | 3 | 10% | 17 | 57% |
| Dispenser | 0 | 0% | 0 | 0% | 4 | 19% | 0 | 0% | 0 | 0% | 1 | 5% | 16 | 76% |
| Submersible Turbine Pump | 0 | 0% | 0 | 0% | 1 | 17% | 0 | 0% | 0 | 0% | 0 | 0% | 5 | 83% |
| Delivery Problem | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% | 0 | 0% |
| Other | 0 | 0% | 0 | 0% | 4 | 11% | 0 | 0% | 2 | 5% | 6 | 16% | 25 | 68% |

| SOURCE | NUMBER | PERCENTAGE |
|-----------|--------|------------|
| Tank | 17 | 20% |
| Piping | 28 | 32% |
| Dispenser | 21 | 24% |
| STP | 6 | 7% |
| Delivery | 0 | 0% |
| Other | 31 | 36% |

Note: Throughout the reporting period, the BUSTR (Bureau of Underground Storage Tank Regulations) staff gathers various information submitted from various sources in the form of , reports and other information from consultants, inspectors, the Ohio Environmental Protection Agency and BUSTR certified inspectors and installers. The information, pertaining to the release from USTs, is entered by BUSTR personnel into a database.

The Bureau of Underground Storage Tank Regulations staff employ the “Grant Guidelines To States For Implementing The Public Information Provision Of the Energy Act Of 2005” in order to classify all the data entered into the OTTER (“Ohio Tank Tracking & Environmental Review”) database. All data used to compile this report was retrieved from the OTTER database. The data reported from consultants has not been verified. Eight (8) types of leak sources (e.g., tank, pipe, dispenser, etc.) have been identified for the eighty-five (85) releases.

In the event specific site release information found in this report is required, please contact the Bureau of Underground Storage Tank Regulations by calling (614)752-7938 or send your inquiry via e-mail to websfm@com.state.oh.us.

Updated 12.31.09