



Department  
of Commerce

Ohio Board of Building Standards

John R. Kasich, Governor  
Jacqueline T. Williams, Director

# 2018 BBS Continuing Education Course Listing Effective June 13, 2018

**Ohio Board of Building Standards**  
6606 Tussing Road  
Reynoldsburg, OH 43068-9009

**Gerald O. Holland**, Chairman

An Equal Opportunity Employer and Service Provider

614-644-2613  
Fax 614 -644-3147  
TTY/TDD 800-750-0750  
com.ohio.gov

Course Number	Course Name	Sponsor	Contact Name	Phone	Email	Certifications (Hours)
BBS2018-001	Grounding & Bonding	IEC of Greater Cincinnati	Kevin Collins	(513) 542-0400	kcollins@iec-cincy.com	BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0)
BBS2018-002	Calculations	IEC of Greater Cincinnati	Kevin Collins	(513) 542-0400	kcollins@iec-cincy.com	BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), ESI(3.0), RBO(3.0), RPE(3.0), RBI(3.0)
BBS2018-003	The Inspection Process (Jan)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-004	The Inspection Process (Feb)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-005	The Inspection Process (Mar)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-006	The Inspection Process (Apr)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-007	The Inspection Process (May)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-008	The Inspection Process (Jun)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-009	The Inspection Process (July)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-010	The Inspection Process (Aug)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-011	The Inspection Process (Sep)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-012	The Inspection Process (Oct)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-013	The Inspection Process (Nov)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-014	The Inspection Process (Dec)	DIC/BCC	Paul Wilson	(614) 728-5293		BI(1.0), BO(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0)
BBS2018-015	Residential Requirements, Luminaries Receptacles & Switches	IEC of Greater Cincinnati	Kevin Collins	(513) 542-0400	kcollins@iec-cincy.com	BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0)
BBS2018-016	Health Care / Emergency Equipment & Power	IEC of Greater Cincinnati	Kevin Collins	(513) 542-0400	kcollins@iec-cincy.com	BO(3.0), MPE(3.0), EPE(3.0), BI(3.0), FPI(3.0), ESI(3.0)
BBS2018-017	Pools, Fountains, Marinas, Boatyards & Docking Facilities	IEC of Greater Cincinnati	Kevin Collins	(513) 542-0400	kcollins@iec-cincy.com	BI(3.0), BO(3.0), EPE(3.0), ESI(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0)
BBS2018-018	Bonding & Grounding	Ron Tusing & Associates	Ron Tusing	(419) 668-7688	ron@rontusing.com	ESI(10.0)
BBS2018-019	Plumbing Code & Code Updates (Sections 101-315) (Day 1)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	PPE(5.0), PI(5.0), RPI(5.0)
BBS2018-020	Plumbing Code & Code Updates (Sections 401-505) (Day 2)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	PPE(5.0), PI(5.0), RPI(5.0)
BBS2018-021	Plumbing Code & Code Updates (Sections 601-804) (Day 3)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	PPE(5.0), PI(5.0), RPI(5.0)

BBS2018-022	Plumbing Code & Code Updates (Sections 901-1004) (Day 4)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	PPE(5.0), PI(5.0), RPI(5.0)
BBS2018-023	Plumbing Code & Code Updates (Sections 1101-1203) (Day 5)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	PPE(5.0), PI(5.0), RPI(5.0)
BBS2018-024	ESI Training & Update Course (Articles 100-324) (Day 1)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	BI(5.0), BO(5.0), ESI(5.0), MPE(5.0), RBI(5.0), RBO(5.0), EPE(5.0)
BBS2018-025	ESI Training & Update Course (Articles 100-324) (Day 2)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	BI(5.0), BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBI(5.0), RBO(5.0)
BBS2018-026	ESI Training & Update Course (Articles 100-324) (Day 3)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	BI(5.0), BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBI(5.0), RBO(5.0)
BBS2018-027	ESI Training & Update Course (Articles 100-324) (Day 4)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	BI(5.0), BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBI(5.0), RBO(5.0)
BBS2018-028	ESI Training & Update Course (Articles 100-324) (Day 5)	Howard Sonenstein Training Agency 253	Howard Sonenstein	(440) 442-6613	howardsonenstein@aol.com	BI(5.0), BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBI(5.0), RBO(5.0)
BBS2018-029	Ohio Portable Fire Extinguishers (Online)	Fire Tech Productions Inc	Mary Harbach	(937) 434-3473	info@firetech.com	BO(3.0), MPE(3.0), BI(3.0), FPI(3.0)
BBS2018-030	Ohio Fire Pumps (Online)	Fire Tech Productions Inc	Mary Harbach	(937) 434-3473	info@firetech.com	BO(4.0), BI(4.0), MPE(4.0), FPI(4.0)
BBS2018-031	Ohio Automatic Sprinkler & Standpipe Systems (Online)	Fire Tech Productions Inc	Mary Harbach	(937) 434-3473	info@firetech.com	BO(5.0), MPE(5.0), BI(5.0), FPI(5.0)
BBS2018-032	Enforcement of the Code	BOCONEO (Raymond Sack)	Raymond Sack	(440) 943-7115	rsack@cityofwickliffe.com	ESI(2.0), BI(2.0), BO(2.0), EPE(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0)
BBS2018-033	Through Penetration Firestopping	3M Fire Protection Products	Brian Chenevey	(517) 902-6908	bchenevey@mmm.com	BI(2.5), BO(2.5), EPE(2.5), FPI(2.5), LPE(2.5), MPE(2.5), MI(2.5), MCPE(2.5), NRIUI(2.5), PI(2.5), PPE(2.5), RBI(2.5), RBO(2.5), REPE(2.5), RIUI(2.5), RMI(2.5), RPE(2.5), RPI(2.5)
BBS2018-034	Code Consistency Committee Roundtable (Jan 17)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-035	Code Consistency Committee Roundtable (Feb 21)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-036	Code Consistency Committee Roundtable (Mar 21)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)

BBS2018-037	Code Consistency Committee Roundtable (Apr 18)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-038	Code Consistency Committee Roundtable (May 16)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-039	Code Consistency Committee Roundtable (Jun 20)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-040	Code Consistency Committee Roundtable (Jul 18)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-041	Code Consistency Committee Roundtable (Aug 15)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-042	Code Consistency Committee Roundtable (Sept 19)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-043	Code Consistency Committee Roundtable (Oct 17)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-044	Code Consistency Committee Roundtable (Nov 21)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)

BBS2018-045	Code Consistency Committee Roundtable (Dec 19)	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-046	2013 RCO Chapter 113 Existing Buildings	Institute For Professional Education	Paul Fussner	(216) 299-9367	pfussner.ipe@att.net	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-047	2017 NEC Article 250	Institute For Professional Education	Paul Fussner	(216) 299-9367	pfussner.ipe@att.net	BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0)
BBS2018-048	2017 NEC Articles 90 - 225	Institute For Professional Education	Paul Fussner	(216) 299-9367	pfussner.ipe@att.net	BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0)
BBS2018-049	2017 NEC Articles 230 - 450	Institute For Professional Education	Paul Fussner	(216) 299-9367	pfussner.ipe@att.net	BO(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0)
BBS2018-050	30 Hour Home Study Course (NEC 2017)	Institute For Professional Education	Paul Fussner	(216) 299-9367	pfussner.ipe@att.net	BO(30.0), EPE(30.0), ESI(30.0), MPE(30.0), RBO(30.0), RPE(30.0)
BBS2018-051	Ohio Fire Service Mains (Online)	Fire Tech Productions Inc	Mary Harbach	(937) 434-3473	info@firetech.com	BO(3.0), FPI(3.0), MPE(3.0), PI(3.0), PPE(3.0), BI(3.0)
BBS2018-052	Ohio Fire Alarm & Detection Equipment (Online)	Fire Tech Productions Inc	Mary Harbach	(937) 434-3473	info@firetech.com	BO(3.0), EPE(3.0), FPI(3.0), MPE(3.0), BI(3.0)
BBS2018-053	2017 Analysis of Changes, Part 1	Winkelectric	Clifford Winker	(440) 346-4125	winkelectric@hotmail.com	EPE(5.0), ESI(5.0), MPE(5.0)
BBS2018-054	2017 Analysis of Changes, Part 2	Winkelectric	Clifford Winker	(440) 346-4125	winkelectric@hotmail.com	EPE(5.0), ESI(5.0), MPE(5.0)
BBS2018-055	2017 NEC Monthly Meeting -Hazardous Locations (Jan 10)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-056	2017 NEC Monthly Meeting -Health Care Facilities (Feb 14)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-057	2017 NEC Monthly Meeting- Fairs / Carnivals (Mar 14)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-058	2017 NEC Monthly Meeting -Pools / Spas (Apr 11)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-059	2017 NEC Monthly Meeting -Field Procedures (May 9)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-060	2017 NEC Monthly Meeting -Grounding & Bonding (June13)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-061	2017 NEC Monthly Meeting -Separately Derived Systems (Aug 8)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-062	2017 NEC Monthly Meeting -Sign / Outline Lighting (Sept 12)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-063	2017 NEC Monthly Meetings -Services (Oct 10)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RPE(2.0), RBO(2.0)
BBS2018-064	2017 NEC Monthly Meeting- Approved Testing Agencies (Nov 14)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), RBO(2.0), RPE(2.0), MPE(2.0)
BBS2018-065	2017 NEC Monthly Meeting -Residential Wiring Methods (Dec 12)	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)

BBS2018-066	Understanding the NEC 2017 (Art. 90-110)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-067	Understanding the NEC 2017 (Art. 200-215)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-068	Understanding the NEC 2017 (Art. 220-225)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-069	Understanding the NEC 2017 (Art. 230-240)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-070	Understanding the NEC 2017 (Art. 250-285)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-071	Understanding the NEC 2017 (Art. 300-340)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-072	Understanding the NEC 2017 (Art. 342-393)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-073	Understanding the NEC 2017 (Art. 400-424)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-074	Understanding the NEC 2017 (Art. 430-480)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-075	Understanding the NEC 2017 (Art. 500-590)	Local 38 - Cleveland JATC	William Brendza	(216) 573-0400	director@cejatc.org	ESI(3.0)
BBS2018-076	Electrical Code Review (Jan 9)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0), BI(2.0), BO(2.0), EPE(2.0), ESI(2.0)
BBS2018-077	Electrical Code Review (Feb 13)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0), EPE(2.0)
BBS2018-078	Electrical Code Review (Mar 13)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-079	Electrical Code Review (Apr 10)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-080	Electrical Code Review (May 8)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-081	Electrical Code Review (Jun 12)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-082	Electrical Code Review (Jul 10)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-083	Electrical Code Review (Aug 14)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-084	Electrical Code Review (Sept 11)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-085	Electrical Code Review (Oct 9)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)

BBS2018-086	Electrical Code Review (Nov 13)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-087	Electrical Code Review (Dec 11)	IAEI - NW Division	Michael Farrell	(419) 213-2981	mfarrell@co.lucas.oh.us	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), MPE(2.0), MI(2.0), MCPE(2.0), RBI(2.0), RBO(2.0), RMI(2.0), RPE(2.0)
BBS2018-088	2017 NEC Changes & Updates	John M Labriola	John Labriola	(330) 497-6309	summitcbo@yahoo.com	BO(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0)
BBS2018-089	2-Hr. PPT Review of RCO – Chapter 3401.1(2) (1)	Institute For Professional Education	Paul Fussner	(216) 299-9367	pfussner.ipe@att.net	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0)
BBS2018-090	Polyurethane Spray Form from Processing to Code Application	Nu Wool Co	Robert DeVries	(616) 669-0100	rdevries@nuwool.com	BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-091	Plans Examiner Roundtable Discussion (Feb 21)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-092	Plans Examiner Roundtable Discussion (Mar 21)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-093	Plans Examiner Roundtable Discussion (Apr 18)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-094	Plans Examiner Roundtable Discussion (May 16)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-095	Plans Examiner Roundtable Discussion (Jun 20)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-096	Plans Examiner Roundtable Discussion (Sep 19)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-097	Plans Examiner Roundtable Discussion (Oct 17)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-098	Plans Examiner Roundtable Discussion (Nov 21)	BOCONEO - Paul Kowalczyk	Paul Kowalczyk	(216) 381-0400	pkowalczyk@seuclid.com	EPE(1.0), MPE(1.0), MCPE(1.0), PPE(1.0)
BBS2018-099	BBS Update	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.5), BO(1.5), EPE(1.5), FPI(1.5), LPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), REPE(1.5), RIUI(1.5), RMI(1.5), RPE(1.5), RPI(1.5)
BBS2018-100	2017 Analysis of the NEC Code Changes -- Ch. 1-4	MECA	Steve Glaser	(937) 264-0418	laurameca@aol.com	BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), REPE(5.0), RPE(5.0)
BBS2018-101	2017 Analysis of the NEC Code Changes -- Ch. 5-9	MECA	Steve Glaser	(937) 264-0418	laurameca@aol.com	BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), REPE(5.0), RPE(5.0)
BBS2018-102	2017 OBC Update Life and Safety	The Preview Group Inc	Sarah Rice	(513) 621-2109	srice@preview-group.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-103	2017 OBC Update (Fire & Life Safety)	The Preview Group Inc	Sarah Rice	(513) 621-2109	srice@preview-group.com	BO(4.0), MPE(4.0), BI(4.0), FPI(4.0)
BBS2018-104	Analysis of 2017 Code Changes Part 1	Central Electric Inspection Bureau	John Grivensky	(330) 744-5238	centralelectricinspection@yahoo.com	ESI(5.0)
BBS2018-105	Analysis of 2017 Code Changes Part 2	Central Electric Inspection Bureau	John Grivensky	(330) 744-5238	centralelectricinspection@yahoo.com	ESI(5.0)
BBS2018-106	An Overview of NFPA (NEC) Part 1	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)

BBS2018-107	An Overview of NFPA (NEC) Part 2	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-108	An Overview of NFPA (NEC) Part 3	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-109	An Overview of NFPA (NEC) Part 4	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-110	An Overview of NFPA (NEC) Part 5	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-111	An Overview of NFPA (NEC) Part 6	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-112	An Overview of NFPA (NEC) Part 7	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-113	An Overview of NFPA (NEC) Part 8	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-114	An Overview of NFPA (NEC) Part 9	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-115	An Overview of NFPA (NEC) Part 10	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-116	An Overview of NFPA (NEC) Part 11	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-117	An Overview of NFPA (NEC) Part 12	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-118	2017 NEC -- Major Changes Roundtable Part 1	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-119	2017 NEC -- Major Changes Roundtable Part 2	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-120	2017 NEC -- Major Changes Roundtable Part 3	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-121	2017 NEC -- Major Changes Roundtable Part 4	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-122	Single Stack Vent Systems Part 1	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0), PI(1.0)
BBS2018-123	Single Stack Vent Systems Part 2	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), PI(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RMI(1.0), RPE(1.0), PPE(1.0)
BBS2018-124	Basic Overview Provisions for Storm Shelters OPBC	DIC/BCC	Paul Wilson	(614) 728-5293		



BBS2018-125	Chapter 3,5 and 6 of the Ohio Building Code	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), FPI(3.0), FPPE(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0)
BBS2018-126	Significant Changes of the 2017 NEC 1/10/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-127	Significant Changes of the 2017 NEC 2/14/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RMI(2.0), RPE(2.0)
BBS2018-128	Significant Changes of the 2017 NEC 3/14/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-129	Significant Changes of the 2017 NEC 4/11/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-130	Significant Changes of the 2017 NEC 5/9/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-131	Significant Changes of the 2017 NEC 6/13/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-132	Significant Changes of the 2017 NEC 9/12/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-133	Significant Changes of the 2017 NEC 10/10/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-134	Significant Changes of the 2017 NEC 11/14/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-135	Significant Changes of the 2017 NEC 12/12/2018	IAEI - Central Ohio Division	Ralph Hoffman	(740) 625-6575	r.hoffman@ieee.org	BO(2.0), EPE(2.0), ESI(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RPE(2.0)
BBS2018-136	Grounding and Bonding/Photovoltaic Systems/Utilities and PV Interconnects	IAEI - SW Ohio Division	Lorenzo Adam	(513) 229-8520	ladam@masonoh.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), MPE(6.0), RBO(6.0), REPE(6.0), RPE(6.0)
BBS2018-137	Monthly Seminar/Meeting (Jan 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-138	Monthly Seminar/Meeting (Feb 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-139	Monthly Seminar/Meeting (Mar 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-140	Monthly Seminar/Meeting (Apr 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-141	Monthly Seminar/Meeting (May 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-142	Monthly Seminar/Meeting (Sept 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-143	Monthly Seminar/Meeting (Oct 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)

BBS2018-144	Monthly Seminar/Meeting (Nov 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-145	Monthly Seminar/Meeting (Dec 2018)	GCEA	Terrence Eibel	(859) 512-5244	gcea01@fuse.net	BO(1.0), EPE(1.0), ESI(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-146	Chapters 3 and 5 OBC 2017	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), FPI(2.0), FPPE(2.0), LPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), PI(2.0), PPE(2.0)
BBS2018-147	Hoover Treated Wood Basic	Hoover Treated Wood Products	Jim Gogolski	(706) 990-8963	jpgogolski@frtw.com	RBO(1.0), REPE(1.0), RIUI(1.0), RPE(1.0), BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), NRIUI(1.0), PPE(1.0), RBI(1.0)
BBS2018-148	Hoover Treated Wood Extended	Hoover Treated Wood Products	Jim Gogolski	(706) 990-8963	jpgogolski@frtw.com	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), FPI(2.0), FPPE(2.0), LPE(2.0), MPE(2.0), NRIUI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), REPE(2.0), RIUI(2.0), RPE(2.0)
BBS2018-149	Hoover Treated Wood IBC	Hoover Treated Wood Products	Jim Gogolski	(706) 990-8963	jpgogolski@frtw.com	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), FPI(3.0), FPPE(3.0), LPE(3.0), MPE(3.0), NRIUI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RPE(3.0)
BBS2018-150	Hoover Treated Wood All Construction	Hoover Treated Wood Products	Jim Gogolski	(706) 990-8963	jpgogolski@frtw.com	BI(4.0), BO(4.0), BPE(4.0), EPE(4.0), FPI(4.0), FPPE(4.0), LPE(4.0), MPE(4.0), NRIUI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RPE(4.0)
BBS2018-151	Significant Changes to the 2017 National Electric Code	Mansfield Area Electrical JATC	William Thompson	(419) 526-4688	wthompson@ibew688.org	ESI(8.0), BO(8.0), BI(8.0), EPE(8.0), RBO(8.0), RBI(8.0)
BBS2018-152	Basic Overview of Provisions for Storm Shelters in OBC and ICC 500	State of Ohio, Commerce, DIC	Yeong-Tarng Jiang	(614) 644-3492	ytjiang@com.state.oh.us	BO(3.0), BI(3.0), MPE(3.0)
BBS2018-153	2018 BBS Meeting (Jan 19)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-154	2018 BBS Meeting (March 2)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-155	2018 BBS Meeting (April 13)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)

BBS2018-156	2018 BBS Meeting (June 1)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-157	2018 BBS Meeting (July 13)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0)
BBS2018-158	2018 BBS Meeting (Aug 24)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-159	2018 BBS Meeting (Oct 5)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-160	2018 BBS Meeting (Nov 9)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-161	2018 BBS Meeting (Dec 14)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), LPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RIUI(1.0), RMI(1.0), RPE(1.0), RPI(1.0)
BBS2018-162	Building Code Meetings and Updates (Jan 3)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), REPE(1.0), RMI(1.0), RPE(1.0)
BBS2018-163	Building Code Meeting and Updates (Feb 7)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), PI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-164	Building Code Meeting and Updates (March 7)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-165	Building Code Meeting and Updates (April 4)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-166	Building Code Meeting and Updates (May 2)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RPE(1.0), RMI(1.0)
BBS2018-167	Building Code Meeting and Updates (June 6)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), FPI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)

BBS2018-168	Building Code Meeting and Updates (July 4)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-169	Building Code Meeting and Updates (Aug 1)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-170	Building Code Meeting and Updates (Sept 5)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-171	Building Code Meeting and Updates (Oct 3)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), MCPE(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-172	Building Code Meeting and Updates (Nov 7)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-173	Building Code Meeting and Updates (Dec 5)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BI(1.0), BO(1.0), ESI(1.0), MPE(1.0), MI(1.0), RBI(1.0), RBO(1.0), RMI(1.0), RPE(1.0)
BBS2018-174	Electrical Code Meeting and Updates (Jan 10)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0), RPE(1.0)
BBS2018-175	Electrical Code Meeting and Updates (Feb14)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-176	Electrical Code Meeting and Updates (March 14)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-177	Electrical Code Meeting and Updates (April 11)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-178	Electrical Code Meeting and Updates (May 9)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-179	Electrical Code Meeting and Updates (June 13)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-180	Electrical Code Meeting and Updates (July 11)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-181	Electrical Code Meeting and Updates (Aug 8)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-182	Electrical Code Meeting and Updates (Sept 12)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-183	Electrical Code Meeting and Updates (Oct 10)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-184	Electrical Code Meeting and Updates (Nov 14)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-185	Electrical Code Meeting and Updates (Dec 12)	National Inspection	Scott Young	(937) 433-4642	plans@natinspect.com	BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBO(1.0), REPE(1.0)
BBS2018-186	Practical Inspection Techniques for Automatic Sprinkler Systems	BOCONEO (Philip Seyboldt)	Philip Seyboldt	(216) 701-1431	pseyboldt@sbcglobal.net	BI(3.0), BO(3.0), BPE(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), RBI(3.0), RBO(3.0), RPE(3.0)
BBS2018-187	First Responder Radio Coverage Code Requirements Part 1	JDRM Engineering Inc	Steven Wheeler	(419) 824-2400	swheeler@jdrm.com	BO(1.0), BI(1.0), MPE(1.0), FPI(1.0), FPPE(1.0)

BBS2018-188	First Responder Radio Coverage Code Requirements Part 2	JDRM Engineering Inc	Steven Wheeler	(419) 824-2400	swheeler@jdrm.com	BO(0.5), MPE(0.5), BI(0.5), FPI(0.5), FPPE(0.5)
BBS2018-189	First Responder Radio Coverage Code Requirements Part 3	JDRM Engineering Inc	Steven Wheeler	(419) 824-2400	swheeler@jdrm.com	BO(0.5), MPE(0.5), BI(0.5), FPI(0.5), FPPE(0.5)
BBS2018-190	Round Table Discussion of Mechanical and Residential Codes Spring 2018	City of Toledo - Charles Sutphin	Charles Sutphin	(419) 345-7010	chazmsut@bex.net	BI(2.5), BO(2.5), BPE(2.5), FPI(2.5), FPPE(2.5), MPE(2.5), MI(2.5), MCPE(2.5), RBI(2.5), RBO(2.5), RMI(2.5), RPE(2.5)
BBS2018-191	Round Table Discussion of Mechanical and Residential Codes Fall 2018	City of Toledo - Charles Sutphin	Charles Sutphin	(419) 345-7010	chazmsut@bex.net	BI(2.5), BO(2.5), BPE(2.5), FPI(2.5), FPPE(2.5), MPE(2.5), MI(2.5), MCPE(2.5), RBI(2.5), RBO(2.5), RMI(2.5), RPE(2.5)
BBS2018-192	Administering OBBC; BBS Updates; Understanding the Code (May)	Cleveland Plumbing Industry Promotion	Thomas Wanner	(216) 459-0770	twanner@mapic.org	BI(10.0), BO(10.0), BPE(10.0), EPE(10.0), FPI(10.0), FPPE(10.0), MPE(10.0), MI(10.0), MCPE(10.0), NRIUI(10.0), PI(10.0), PPE(10.0), RBI(10.0), RBO(10.0), RIUI(10.0), RMI(10.0), RPE(10.0)
BBS2018-193	Administering OBBC; BBS Updates; Understanding the Code (September)	Cleveland Plumbing Industry Promotion	Thomas Wanner	(216) 459-0770	twanner@mapic.org	BI(10.0), BO(10.0), BPE(10.0), EPE(10.0), FPI(10.0), FPPE(10.0), MPE(10.0), MI(10.0), MCPE(10.0), NRIUI(10.0), PI(10.0), PPE(10.0), RBI(10.0), RBO(10.0), RIUI(10.0), RMI(10.0), RPE(10.0)
BBS2018-194	Navigating the Plumbing Code	City of Columbus (James A. Richardson Jr.)	James Richardson, Jr.	(614) 645-6340	jarichardson@columbus.gov	BI(1.0), BO(1.0), BPE(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0)
BBS2018-195	NFPA 20 Ch. 9 and NEC Article 695	Herb Porter Code Consultants	Herbert Porter	(330) 573-8723	weilerot@gmail.com	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0)
BBS2018-196	Deck Building 101- Beginner's Course Online Guide	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	
BBS2018-197	Changes to the 2017 NEC Article 430, 700, 701, 702	Bob Carter Electrical Contracting Inc	Robert Carter	(740) 407-4211	rocarter1972@live.com	ESI(5.0)
BBS2018-198	Changes to the 2017 NEC Articles 230, 406, 408, 410	Bob Carter Electrical Contracting Inc	Robert Carter	(740) 407-4211	rocarter1972@live.com	ESI(5.0)
BBS2018-199	Changes to the 2017 NEC Articles 300-310	Bob Carter Electrical Contracting Inc	Robert Carter	(740) 407-4211	rocarter1972@live.com	ESI(5.0)
BBS2018-200	Changes to the 2017 NEC Articles 200, 210-215	Bob Carter Electrical Contracting Inc	Robert Carter	(740) 407-4211	rocarter1972@live.com	ESI(5.0)
BBS2018-201	Changes to the 2017 NEC Articles 220-250	Bob Carter Electrical Contracting Inc	Robert Carter	(740) 407-4211	rocarter1972@live.com	ESI(5.0)
BBS2018-202	Changes to the 2017 NEC Articles 100, 110, 240	Bob Carter Electrical Contracting Inc	Robert Carter	(740) 407-4211	rocarter1972@live.com	ESI(5.0)
BBS2018-203	Health Care Facilities	Dayton Electrical JATC	Eric Gray	(937) 264-2052	egray@ibew82.org	MPE(6.0), EPE(6.0), ESI(6.0), RPE(6.0)
BBS2018-204	Pools and Spas, Common Code Violations	Dayton Electrical JATC	Eric Gray	(937) 264-2052	egray@ibew82.org	EPE(6.0), ESI(6.0), MPE(6.0), RPE(6.0)

BBS2018-205	Code Requirements for Existing Buildings	Carl Lamping	Carl Lamping	(513) 543-5473	clamping@fuse.net	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-206	CBO Code Summit Winter	MVBOC - Jene Gaver	Jene Gaver	(937) 324-7390	jgaver@springfieldohio.gov	BO(2.0), BI(2.0), MPE(2.0)
BBS2018-207	CBO Code Summit Spring	MVBOC - Jene Gaver	Jene Gaver	(937) 324-7390	jgaver@springfieldohio.gov	BO(2.0), BI(2.0), MPE(2.0)
BBS2018-208	CBO Code Summit Summer	MVBOC - Jene Gaver	Jene Gaver	(937) 324-7390	jgaver@springfieldohio.gov	BO(2.0), BI(2.0), MPE(2.0)
BBS2018-209	CBO Code Summit Fall	MVBOC - Jene Gaver	Jene Gaver	(937) 324-7390	jgaver@springfieldohio.gov	BO(2.0), BI(2.0), MPE(2.0)
BBS2018-210	ICC Reinforced Concrete Special Inspector Certification Test Academy	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BO(15.0), BI(15.0), MPE(15.0), RBO(15.0), RPE(15.0)
BBS2018-211	Mandatory Commissioning Requirements of IECC 2012/ASHRAE 90.1-2010	Heapy Engineering	Alec Carnes	(937) 224-0861	lddahm@heapy.com	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), PI(1.0), PPE(1.0)
BBS2018-212	Overview of Tornado Shelter in Accordance with OBC 2017 and ICC-500	Schaefer Inc	Steven Schaefer	(513) 542-3300	steve.schaefer@schaefer-inc.com	BI(1.0), BO(1.0), MPE(1.0)
BBS2018-213	RBO Summit Meeting Winter	City of Vandalia	Chris Mastrino	(937) 415-2322	cmastrino@vandaliaohio.org	RBI(2.0), RBO(2.0), RMI(2.0), ESI(2.0), RPE(2.0)
BBS2018-214	RBO Summit Meeting Spring	City of Vandalia	Chris Mastrino	(937) 415-2322	cmastrino@vandaliaohio.org	RBI(2.0), RBO(2.0), RPE(2.0), RMI(2.0), ESI(2.0)
BBS2018-215	RBO Summit Meeting Summer	City of Vandalia	Chris Mastrino	(937) 415-2322	cmastrino@vandaliaohio.org	RBI(2.0), RBO(2.0), RPE(2.0), RMI(2.0), ESI(2.0)
BBS2018-216	RBO Summit Meeting Fall	City of Vandalia	Chris Mastrino	(937) 415-2322	cmastrino@vandaliaohio.org	RBI(2.0), RBO(2.0), RPE(2.0), RMI(2.0), ESI(2.0)
BBS2018-217	2017 NEC Code Changes 2.1	Ohio Electrical Training	Joseph Ponzio	(614) 581-5700	oh.electrical.training@gmail.com	ESI(8.0)
BBS2018-218	2017 NEC Code Changes 2.2	Ohio Electrical Training	Joseph Ponzio	(614) 581-5700	oh.electrical.training@gmail.com	ESI(8.0)
BBS2018-219	2017 NEC Code Changes 2.3	Ohio Electrical Training	Joseph Ponzio	(614) 581-5700	oh.electrical.training@gmail.com	ESI(8.0)
BBS2018-220	2017 NEC Code Changes 2.4	Ohio Electrical Training	Joseph Ponzio	(614) 581-5700	oh.electrical.training@gmail.com	ESI(6.0)
BBS2018-221	Boring and Notching in Wood-Frame Construction	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-222	Concrete Repair Design	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-223	Concrete Repair Installation	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-224	Diaphragm Design with 2015 SDPWS	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-225	Shearwall Design with 2015 SDPWS	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-226	Strengthening with Fiber-Reinforced Polymer	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-227	Strong-Wall Shearwalls	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBO(1.0), RPE(1.0), RBI(1.0)

BBS2018-228	Understanding Moment Frames	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(2.0), BO(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-229	Wall Bracing for Wind Design with 2015 IRC	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-230	Wind Design with the 2015 WFCM	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-231	Wood, Steel, and Concrete Deterioration	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-232	Indirect Waste	City of Columbus (James A. Richardson Jr.)	James Richardson, Jr.	(614) 645-6340	jarichardson@columbus.gov	BI(1.0), BO(1.0), BPE(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0)
BBS2018-233	Traps & Interceptors	City of Columbus (James A. Richardson Jr.)	James Richardson, Jr.	(614) 645-6340	jarichardson@columbus.gov	BI(1.0), BO(1.0), BPE(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0)
BBS2018-234	Deck Building 101 - Beginner's Course (online)	Simpson Strong-Tie (Ian McCallion)	Ian McCallion	(925) 560-2631	imccallion@strongtie.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-235	Important Structural Changes in the 2017 Ohio Building Code	Schaefer Inc	Steven Schaefer	(513) 542-3300	steve.schaefer@schaefer-inc.com	BI(2.0), BO(2.0), BPE(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-236	Significant Changes to the 2015 IBC	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(3.0), BO(3.0), BPE(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), NRIUI(3.0)
BBS2018-237	Significant Changes to the 2015 IMC	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.5), BO(1.5), BPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5)
BBS2018-238	Significant Changes to the 2015 IPC	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.5), BO(1.5), BPE(1.5), MPE(1.5), PI(1.5), PPE(1.5)
BBS2018-239	The Ohio Ethics Law: Can I Do That?	Ohio Ethics Commission	Susan Willeke	(614) 466-7090	susan.willeke@ethics.state.oh.us	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0)
BBS2018-240	OBC Plumbing Code Updates	DIC/BCC Plumbing Section	Lance Begoon	(614) 644-3153	lance.begoon@com.ohio.gov	BO(4.0), MPE(4.0), PI(4.0), PPE(4.0)
BBS2018-241	Stationary Fire Pumps 101	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	MPE(1.0), BO(1.0), BI(1.0), FPI(1.0)
BBS2018-242	Significant Changes to NFPA 72-2016	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-243	What Codes to Apply to Fire Alarm Systems	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-244	Fire Sprinklers 101	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-245	NFPA 25-2014 Update and Significant Changes	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BI(1.0), PPE(1.0), FPI(1.0), PI(1.0), RBO(1.0), RBI(1.0), BO(1.0)
BBS2018-246	NFPA 25 and 72: Compliance Need Not Break the Bank	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-247	NFPA 25 -- Misunderstood, Misapplied, and Misinterpreted	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BI(1.0), FPI(1.0), BO(1.0)

BBS2018-248	Two-Way Radio Enhancement Systems	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-249	Understanding the UL Monitoring Systems Certification Program	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BO(1.0), MPE(1.0), BI(1.0), FPI(1.0)
BBS2018-250	Understanding Mass Notification Systems	Fire Code Academy	Randall Hormann	(800) 771-3403	randyh@firecodeacademy.com	BI(1.0), FPI(1.0), BO(1.0), EPE(1.0), MPE(1.0)
BBS2018-251	NEC 2017 Analysis of Changes 2/27/18	IAEI - Akron Division	Oran Post	(330) 715-6309	op317@sbcglobal.net	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-252	NEC 2017 Analysis of Changes 3/27/18	IAEI - Akron Division	Oran Post	(330) 715-6309	op317@sbcglobal.net	BPE(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0), BI(2.0), BO(2.0)
BBS2018-253	NEC 2017 Analysis of Changes 4/24/18	IAEI - Akron Division	Oran Post	(330) 715-6309	op317@sbcglobal.net	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-254	NEC 2017 Analysis of Changes 5/22/18	IAEI - Akron Division	Oran Post	(330) 715-6309	op317@sbcglobal.net	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-255	NEC 2017 Analysis of Changes 6/26/18	IAEI - Akron Division	Oran Post	(330) 715-6309	op317@sbcglobal.net	BI(2.0), BO(2.0), BPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0), EPE(2.0)
BBS2018-256	NEC 2017 Analysis of Changes 7/27/18	IAEI - Akron Division	Oran Post	(330) 715-6309	op317@sbcglobal.net	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-257	Practical NEC Training	Timothy Pool LLC	Timothy Pool	(440) 497-0060	timpool@sbcglobal.net	BO(10.0), EPE(10.0), ESI(10.0), MPE(10.0)
BBS2018-258	Ohio Elevator Review	State of Ohio, DIC, Elevators	Chip Updyke	(513) 509-4831	cupdyke@com.state.oh.us	BI(2.0), BO(2.0), BPE(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-259	How to Use the NEC	Ohio Certificate Renewal	Harold Plant	(614) 519-1698	harold2112@att.net	BO(4.0), BPE(4.0), EPE(4.0), ESI(4.0), MPE(4.0), RBO(4.0), RPE(4.0)
BBS2018-260	How to Use the NEC and Health Care Facilities	Ohio Certificate Renewal	Harold Plant	(614) 519-1698	harold2112@att.net	BO(8.0), BPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0), EPE(8.0)
BBS2018-261	How to Use the NEC/Grounding and Bonding Services	Ohio Certificate Renewal	Harold Plant	(614) 519-1698	harold2112@att.net	BO(8.0), BPE(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0)
BBS2018-262	How to Use the NEC/Motors	Ohio Certificate Renewal	Harold Plant	(614) 519-1698	harold2112@att.net	BO(8.0), BPE(8.0), EPE(8.0), ESI(8.0), MPE(8.0), RBO(8.0), RPE(8.0)
BBS2018-263	Cold-Formed Steel and Curtain Wall Connections	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BO(1.0), BI(1.0), MPE(1.0)
BBS2018-264	Continuous Load Path: Beyond the Basics of Wood Framing (1 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(1.0), BO(1.0), BPE(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-265	Continuous Load Path: Beyond the Basics of Wood Framing (2 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(2.0), BO(2.0), BPE(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-266	Continuous Load Path: Beyond the Basics of Wood Framing (3 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(3.0), BO(3.0), BPE(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0)
BBS2018-267	Continuous Load Path: Beyond the Basics of Wood Framing (6 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(6.0), BO(6.0), BPE(6.0), MPE(6.0), RBI(6.0), RBO(6.0), RPE(6.0)
BBS2018-268	Deck, Porch, Balcony Framing Connection Seminar (1 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(1.0), BO(1.0), BPE(1.0), MPE(1.0), RBI(1.0), RBO(1.0), RPE(1.0)
BBS2018-269	Deck, Porch, Balcony Framing Connection Seminar (2 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(2.0), BO(2.0), BPE(2.0), MPE(2.0), RBI(2.0), RBO(2.0), RPE(2.0)
BBS2018-270	Deck, Porch, Balcony Framing Connection Seminar (3 hour)	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BI(3.0), BO(3.0), BPE(3.0), MPE(3.0), RBI(3.0), RBO(3.0), RPE(3.0)



BBS2018-271	Natural Gas Fundamentals	Dominion Energy Ohio	Donald MacBride	(234) 380-4282	dona149@dom.com	BI(2.0), BO(2.0), BPE(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0)
BBS2018-272	Understanding the 2009 IECC Ohio Style	Nu Wool Co	Robert DeVries	(616) 669-0100	rdevries@nuwool.com	BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0)
BBS2018-273	Cellulose Insulation: History, Use, and Testing	Nu Wool Co	Robert DeVries	(616) 669-0100	rdevries@nuwool.com	BO(2.0), MPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0)
BBS2018-274	Building Science for Building Officials	Nu Wool Co	Robert DeVries	(616) 669-0100	rdevries@nuwool.com	BO(2.0), BI(2.0), MPE(2.0), RBO(2.0), RPE(2.0), RBI(2.0)
BBS2018-275	Engineered Wood A to Z	American Wood Council (James B Smith)	James Smith	(608) 635-6635	jsmith@awc.org	BO(3.0), MPE(3.0), BI(3.0), RBO(3.0), RPE(3.0), RBI(3.0)
BBS2018-276	OCILB Updates	OCILB	Carol Ross	(614) 644-3494	carol.ross@com.state.oh.us	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0)
BBS2018-277	Maintaining the Integrity of Fire-Rated Construction (with Videos)	INTEK Construction Products Inc	Jeffery Molchan	(216) 398-3300	j.molchan@intekcp.com	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0)
BBS2018-278	Maintaining the Integrity of Fire-Rated Construction	INTEK Construction Products Inc	Jeffery Molchan	(216) 398-3300	j.molchan@intekcp.com	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0)
BBS2018-279	Sizing Category One Venting Systems	Dominion Energy Ohio	Donald MacBride	(234) 380-4282	dona149@dom.com	BI(2.0), BO(2.0), BPE(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0)
BBS2018-280	CSST Gas Tubing System	Dominion Energy Ohio	Donald MacBride	(234) 380-4282	dona149@dom.com	BI(2.0), BO(2.0), BPE(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0)
BBS2018-281	Air for Combustion and Ventilation of Natural Gas Appliances	Dominion Energy Ohio	Donald MacBride	(234) 380-4282	dona149@dom.com	BI(2.0), BO(2.0), BPE(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0), RPI(2.0)
BBS2018-282	Review of the 2015 IFGC	Dominion Energy Ohio	Donald MacBride	(234) 380-4282	dona149@dom.com	BI(3.0), BO(3.0), BPE(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0)

BBS2018-283	OAPI Courses	OAPI (James A Richardson Jr)	James Richardson Jr	(614) 645-6340	jarichardson@columbus.gov	BI(3.0), BO(3.0), BPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), RMI(3.0), RPE(3.0)
BBS2018-284	Plumbing Inspectors Roundtable Discussion February	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-285	Plumbing Inspectors Roundtable Discussion March	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-286	Plumbing Inspectors Roundtable Discussion April	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-287	Plumbing Inspectors Roundtable Discussion May	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-288	Plumbing Inspectors Roundtable Discussion June	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-289	Plumbing Inspectors Roundtable Discussion September	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0), PI(1.0)
BBS2018-290	Plumbing Inspectors Roundtable Discussion October	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-291	Plumbing Inspectors Roundtable Discussion November	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), PPE(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RIUI(1.0)
BBS2018-292	Electrical Inspectors Roundtable Discussion February	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MCPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-293	Electrical Inspectors Roundtable Discussion March	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-294	Electrical Inspectors Roundtable Discussion April	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-295	Electrical Inspectors Roundtable Discussion May	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-296	Electrical Inspectors Roundtable Discussion June	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-297	Electrical Inspectors Roundtable Discussion September	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-298	Electrical Inspectors Roundtable Discussion October	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-299	Electrical Inspectors Roundtable Discussion November	BOCONEO / Michael Gero	Michael Gero	(440) 537-4548	mjgero@sbcglobal.net	BO(1.0), MPE(1.0), EPE(1.0), RBO(1.0), ESI(1.0)
BBS2018-300	BBS Updates	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0)
BBS2018-302	Code Official Institute	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BO(22.0), MPE(22.0), BI(22.0), FPI(22.0), MI(22.0), RBO(22.0), RBI(22.0), RPE(22.0), PI(22.0)

BBS2018-303	Analysis of 2017 NEC Code Changes Part 1	DIC/BCC	Paul Wilson	(614) 728-5293		BO(5.0), MPE(5.0), PPE(5.0), EPE(5.0), MCPE(5.0), BI(5.0), FPI(5.0), MI(5.0), PI(5.0), NRIUI(5.0), RBO(5.0), RPE(5.0), ESI(5.0)
BBS2018-304	Analysis of 2017 NEC Code Changes Part 2	DIC/BCC	Paul Wilson	(614) 728-5293		BO(5.0), MPE(5.0), PPE(5.0), EPE(5.0), MCPE(5.0), BI(5.0), FPI(5.0), MI(5.0), PI(5.0), NRIUI(5.0), ESI(5.0), RBO(5.0), RBI(5.0)
BBS2018-305	2017 NEC Update	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BO(6.0), MPE(6.0), EPE(6.0), ESI(6.0)
BBS2018-306	Analysis of Changes Chapters 1 and 2	OCIB - Mary Ward	Mary Ward	(740) 591-5448	rlw8169@yahoo.com	ESI(2.0)
BBS2018-307	Analysis of Changes Chapter 3	OCIB - Mary Ward	Mary Ward	(740) 591-5448	rlw8169@yahoo.com	ESI(2.0)
BBS2018-308	Analysis of Changes Chapter 4	OCIB - Mary Ward	Mary Ward	(740) 591-5448	rlw8169@yahoo.com	ESI(2.0)
BBS2018-309	Analysis of Changes Chapters 5 and 6	OCIB - Mary Ward	Mary Ward	(740) 591-5448	rlw8169@yahoo.com	ESI(2.0)
BBS2018-310	Analysis of Changes Chapters 7 and 8	OCIB - Mary Ward	Mary Ward	(740) 591-5448	rlw8169@yahoo.com	ESI(2.0)
BBS2018-311	ASHRAE 90.1	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(1.5), BO(1.5), BPE(1.5), EPE(1.5), ESI(1.5), FPI(1.5), FPPE(1.5), MPE(1.5), MI(1.5), MCPE(1.5), NRIUI(1.5), PI(1.5), PPE(1.5), RBI(1.5), RBO(1.5), RIUI(1.5), RMI(1.5), RPE(1.5)
BBS2018-312	Firestopping: Plan Review and Inspection (3 hr version)	Fire Containment Training Service LLC	Brice Miller	(970) 223-4985	brice@firecontainmenttraining.com	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-313	Firestopping: Plan Review and Inspection (4 hr version)	Fire Containment Training Service LLC	Brice Miller	(970) 223-4985	brice@firecontainmenttraining.com	BI(4.0), BO(4.0), BPE(4.0), EPE(4.0), ESI(4.0), FPI(4.0), FPPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), RIUI(4.0), RMI(4.0), RPE(4.0)
BBS2018-314	Firestopping: Plan Review and Inspection (6 hr version)	Fire Containment Training Service LLC	Brice Miller	(970) 223-4985	brice@firecontainmenttraining.com	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), RIUI(6.0), RMI(6.0), RPE(6.0)
BBS2018-315	Firestopping: Plan Review and Inspection (7 hr version)	Fire Containment Training Service LLC	Brice Miller	(970) 223-4985	brice@firecontainmenttraining.com	BI(7.0), BO(7.0), BPE(7.0), EPE(7.0), ESI(7.0), FPI(7.0), FPPE(7.0), MPE(7.0), MI(7.0), MCPE(7.0), NRIUI(7.0), PI(7.0), PPE(7.0), RBI(7.0), RBO(7.0), RIUI(7.0), RMI(7.0), RPE(7.0)
BBS2018-316	Firestopping: Plan Review and Inspection (1 hr version)	Fire Containment Training Service LLC	Brice Miller	(970) 223-4985	brice@firecontainmenttraining.com	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0)

BBS2018-317	Firestopping: Plan Review and Inspection (2 hr version)	Fire Containment Training Service LLC	Brice Miller	(970) 223-4985	brice@firecontainmenttraining.com	BI(2.0), BO(2.0), BPE(2.0), EPE(2.0), ESI(2.0), FPI(2.0), FPPE(2.0), MPE(2.0), MI(2.0), MCPE(2.0), NRIUI(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0), RIUI(2.0), RMI(2.0), RPE(2.0)
BBS2018-318	2017 NEC/IAEI Analysis Part 1	Robert O'Connors	Robert O'Connors	(937) 644-2521	boconno@live.com	BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0)
BBS2018-318	2017 NEC/IAEI Analysis Part 1	Robert O'Connors	Robert O'Connors	(937) 644-2521	chrisoconnors71@gmail.com	BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0)
BBS2018-319	2017 NEC/IAEI Analysis Part 2	Robert O'Connors	Robert O'Connors	(937) 644-2521	boconno@live.com	BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0)
BBS2018-319	2017 NEC/IAEI Analysis Part 2	Robert O'Connors	Robert O'Connors	(937) 644-2521	chrisoconnors71@gmail.com	BO(5.0), EPE(5.0), ESI(5.0), MPE(5.0), RBO(5.0), RPE(5.0)
BBS2018-320	Building Envelope Trained	BES Institute	Patricia Charleston	(877) 688-2374	admin@besinstitute.com	BI(6.0), BO(6.0), MPE(6.0), RBI(6.0), RBO(6.0), RPE(6.0)
BBS2018-321	Building Envelope Certified	BES Institute	Patricia Charleston	(877) 688-2374	admin@besinstitute.com	BI(16.0), BO(16.0), MPE(16.0), RBI(16.0), RBO(16.0), RPE(16.0)
BBS2018-322	Introduction to Ventilation	Panasonic Eco Solutions	Jeff Klonowski	(920) 737-2758	jeffery.klonowski@us.panasonic.com	BO(1.0), BI(1.0), MPE(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0), RMI(1.0)
BBS2018-323	2018 OAPI IPC Changes for the OPC	OAPI (James A Richardson Jr)	James Richardson Jr	(614) 645-6340	jarichardson@columbus.gov	BI(2.0), BO(2.0), BPE(2.0), MPE(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0)
BBS2018-324	New 2017 OBC Fire Alarm Requirements	Cintas Fire Protection	Donald Norris	(513) 346-5901	norrisd@cintas.com	BO(2.0), MPE(2.0), BI(2.0), EPE(2.0), FPI(2.0), MI(2.0)
BBS2018-325	Case Studies for Proper Plan Review and Inspection	Associated Consulting Solutions LLC	Jerry Flanik	(216) 256-3556	skillbuilder64@aol.com	BO(3.0), MPE(3.0), EPE(3.0), MCPE(3.0), BI(3.0), FPI(3.0), MI(3.0), NRIUI(3.0), BPE(3.0), FPPE(3.0), ESI(3.0), RBO(3.0), RPE(3.0)
BBS2018-326	2017 NEC - Major Changes (Conference)	City of Columbus (Sam Cronk)	Sam Cronk	(614) 645-1887	jcusanowsky@columbus.gov	BO(4.0), EPE(4.0), BI(4.0), BPE(4.0), ESI(4.0), FPI(4.0), FPPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), RIUI(4.0), RMI(4.0), RPE(4.0)
BBS2018-327	2017 NEC - Top 10 Changes	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(2.0), BO(2.0), EPE(2.0), ESI(2.0), FPI(2.0), RBI(2.0), RBO(2.0)
BBS2018-328	Ashrae 90.1 for Buildings Except Low Rise Residential	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), MPE(1.0)
BBS2018-329	New Generation of Medium Voltage Switchgear	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), MPE(1.0), RBI(1.0), RBO(1.0)
BBS2018-330	Code Requirements for the Layout and Design of Fire Alarm Systems	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), FPI(4.0), FPPE(4.0), MPE(4.0), RBI(4.0), RBO(4.0)
BBS2018-331	Protecting Critical Circuits from Fire	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), RBI(1.0), RBO(1.0)

BBS2018-332	Requirements for Wind Turbines and Solar Panels	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), RBI(1.0), RBO(1.0)
BBS2018-333	Standby Power Generator Systems	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(1.0), BO(1.0), EPE(1.0), ESI(1.0), FPI(1.0), RBI(1.0), RBO(1.0)
BBS2018-334	NEC 2017: Changes and Updates to the NEC	Electrical League of Ohio	Terri Hanna-Wiehn	(440) 333-5040	terrihanna-wiehn@sbcglobal.net	BI(4.0), BO(4.0), EPE(4.0), ESI(4.0), FPI(4.0), FPPE(4.0), LPE(4.0), MPE(4.0), NRIUI(4.0), RBI(4.0), RBO(4.0), RIUI(4.0), RPE(4.0)
BBS2018-335	Compliant/Noncompliant Drawing Review and Roundtable	OAPI (Jason Shank)	Jason Shank		jshank@plumbers55.com	BI(2.0), BO(2.0), MPE(2.0), PI(2.0), PPE(2.0), RBI(2.0), RBO(2.0)
BBS2018-336	Compliant Uses of Plastic Piping in the OPC	OAPI (Jason Shank)	Jason Shank		jshank@plumbers55.com	BI(1.0), BO(1.0), MPE(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0)
BBS2018-337	Chapter 2 Definitions in the OPC	OAPI (Jason Shank)	Jason Shank		jshank@plumbers55.com	BI(1.0), BO(1.0), MPE(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0)
BBS2018-338	Medical Gas Systems: Installation	OAPI (Jason Shank)	Jason Shank		jshank@plumbers55.com	BI(1.0), BO(1.0), MPE(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0)
BBS2018-339	Medical Gas Systems -- Source Equipment, Certifications and Inspections	OAPI (Jason Shank)	Jason Shank		jshank@plumbers55.com	BI(1.0), BO(1.0), MPE(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0)
BBS2018-340	Backflow History/Starting a Program	OAPI (Jason Shank)	Jason Shank		jshank@plumbers55.com	BI(1.0), BO(1.0), MPE(1.0), RBI(1.0), PI(1.0), PPE(1.0), RBO(1.0)
BBS2018-341	2017 Ohio Fire Code Training	State Fire Marshal	Tracie Boyd	(614) 387-0106	tracie.boyd@com.state.oh.us	BO(3.0), MPE(3.0), BPE(3.0), FPPE(3.0), BI(3.0), FPI(3.0)
BBS2018-342	Analysis of Changes to the 2017 NEC Part 1	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	ESI(2.0), BO(2.0), MPE(2.0), EPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-343	Wall Bracing Round Table	Hamilton County Planning and Development	Robert Eifert	(513) 946-4530	bob.eifert@hamilton-co.org	BPE(1.0), BO(1.0), MPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0), RIUI(1.0)
BBS2018-344	Door Hardware Requirements Round Table	Hamilton County Planning and Development	Robert Eifert	(513) 946-4530	bob.eifert@hamilton-co.org	BPE(1.0), FPPE(1.0), BO(1.0), MCPE(1.0), BI(1.0), FPI(1.0), NRIUI(1.0)
BBS2018-345	Energy Code Requirements Round Table	Hamilton County Planning and Development	Robert Eifert	(513) 946-4530	bob.eifert@hamilton-co.org	NRIUI(1.0), RMI(1.0), BO(1.0), MPE(1.0), BI(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0), RIUI(1.0)
BBS2018-346	Significant Changes to the 2017 OBC for Fire Officials	Hamilton County Planning and Development	Robert Eifert	(513) 946-4530	bob.eifert@hamilton-co.org	BPE(2.0), FPPE(2.0), RMI(2.0), BO(2.0), MPE(2.0), PPE(2.0), EPE(2.0), MCPE(2.0), BI(2.0), FPI(2.0), MI(2.0), NRIUI(2.0), RBO(2.0), RPE(2.0), RBI(2.0)
BBS2018-347	Ohio Firestop Seminar	Hilti	Keith O'Brien	(614) 364-0343	obrieki@hilti.com	BO(3.0), BI(3.0), FPI(3.0), MI(3.0), PI(3.0)
BBS2018-348	Firestop 101	Hilti	Keith O'Brien	(614) 364-0343	obrieki@hilti.com	BI(3.0), FPI(3.0), MI(3.0), PI(3.0)
BBS2018-349	Wind Sesign with ASCE 7-10	Simpson Strong-Tie	Greg Wujcik	(614) 850-4125	gwujcik@strongtie.com	BO(2.0), MCPE(2.0), BI(2.0), RBO(2.0), RPE(2.0), RBI(2.0)
BBS2018-350	All You Wanted to Know About Polymeric Siding	Vinyl Siding Institute	Deina Hashimi	(202) 587-5106	dhashimi@vinylsiding.org	BPE(1.0), BO(1.0), MCPE(1.0), BI(1.0), FPI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-351	Mechanical Code Application and Enforcement	DeBra-Kuempel	Dave Behwe	(513) 527-8124	dbehwe@debra-kuempel.com	BO(3.0), MCPE(3.0), MPE(3.0), BI(3.0), MI(3.0), RBO(3.0)

BBS2018-352	Analysis of Changes to the 2017 NEC Part 2	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-353	Analysis of Changes to the 2017 NEC Part 3	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-354	Analysis of Changes to the 2017 NEC Part 4	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-355	Analysis of Changes to the 2017 NEC Part 5	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	BO(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0), EPE(2.0)
BBS2018-356	Analysis of Changes to the 2017 NEC Part 6	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-357	Analysis of Changes to the 2017 NEC Part 7	IAEI - Western Reserve Division	Mark Rom	(440) 537-0320	run4amps@hotmail.com	BO(2.0), EPE(2.0), ESI(2.0), MPE(2.0), RBO(2.0), RPE(2.0)
BBS2018-358	OBC: Plumbing Code Updates Part 1	DIC/BCC Plumbing Section	Lance Begoon	(614) 644-3153	lance.begoon@com.ohio.gov	BO(2.0), MPE(2.0), PI(2.0), PPE(2.0)
BBS2018-359	OBC: Plumbing Code Updates Part 2	DIC/BCC Plumbing Section	Lance Begoon	(614) 644-3153	lance.begoon@com.ohio.gov	BO(2.0), MPE(2.0), PI(2.0), PPE(2.0)
BBS2018-360	Electronic Plan Review: Roundtable Discussion	MVBOC - Pete Baldauf	Pete Baldauf	(937) 415-2326	esi@vandaliaohio.org	BI(1.0), BO(1.0), BPE(1.0), EPE(1.0), ESI(1.0), FPI(1.0), FPPE(1.0), MPE(1.0), MI(1.0), MCPE(1.0), NRIUI(1.0), PI(1.0), PPE(1.0), RBI(1.0), RBO(1.0), RIUI(1.0), RMI(1.0), RPE(1.0)
BBS2018-361	2017 NEC Changes	JADE Learning LLC	Amy Bonilla	(919) 781-4477	ahbonilla@jadelearning.com	ESI(16.0)
BBS2018-362	Residential Wiring (2017 NEC)	JADE Learning LLC	Amy Bonilla	(919) 781-4477	ahbonilla@jadelearning.com	ESI(8.0)
BBS2018-363	Commercial and Industrial Wiring (2017 NEC)	JADE Learning LLC	Amy Bonilla	(919) 781-4477	ahbonilla@jadelearning.com	ESI(8.0)
BBS2018-364	Wood Wall Bracing (Module 1) Load Path, Lateral Forces and Stiffened Wall (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BO(0.5), BPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5), EPE(0.5), BI(0.5)
BBS2018-365	Wood Wall Bracing (Module 2) History of Wall Bracing and Limits (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-366	Braced Wall Lines	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-367	Wood Wall Bracing (Module 4) Braced Wall Panels (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5), BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5)

BBS2018-368	Wood Wall Bracing (Module 5) Intermittent Bracing Methods (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-368	Wood Wall Bracing (Module 5) Intermittent Bracing Methods (online)	Beavercreek Twp Fire Dept	Robert Treiber	(937) 416-6201	rtreiber@woh.rr.com	
BBS2018-369	Wood Wall Bracing (Module 6) Continuous Sheathing Methods End Conditions (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-370	Wood Wall Bracing (Module 7) Mixing Methods, Interior Finish, and Joists	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-371	Wood Wall Bracing (Module 8) Connections Cripple Wall Foundations (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-372	Wood Wall Bracing (Module 9) Simplified Wall Bracing (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-373	Wood Wall Bracing (Module 10) Wall Bracing Examples 1 and 2 (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-374	Wood Wall Bracing (Module 11) Wall Bracing Example 3 (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-375	Wood Wall Bracing (Module 12) Wall Bracing Example 4 (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)

BBS2018-376	Accessibility Modules (Module 1) Key Definitions for Accessibility (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-377	Accessibility Modules (Module 2) Basis for Technical Requirements (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-378	Accessibility Modules (Module 3) Key Concepts for Accessibility (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-379	Accessibility Modules (Module 4) Exterior Accessible Route (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-380	Accessibility Modules (Module 5) Interior Accessible Route (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-381	Accessibility Modules (Module 6) Accessibility Entry and Egress (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-382	Accessibility Modules (Module 7A) Accessibility in Dwelling and Sleeping Units: Scoping (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	MII(0.5), PI(0.5), NRIUI(0.5), ESI(0.5), RBO(0.5), RPE(0.5), RBI(0.5), RMI(0.5), RIUI(0.5), BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MCPE(0.5), PPE(0.5), REPE(0.5), RPI(0.5)
BBS2018-383	Accessibility Modules (Module 7B) Accessibility in Dwelling and Sleeping Units: Technical (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	MII(0.5), PI(0.5), NRIUI(0.5), ESI(0.5), RBO(0.5), RPE(0.5), RBI(0.5), RMI(0.5), RIUI(0.5), BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), PPE(0.5), REPE(0.5), RPI(0.5), MCPE(0.5)



BBS2018-384	Accessibility Modules (Module 8) Accessibility in Recreational Facilities (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-385	Accessibility Modules (Module 9) Accessibility Plumbing Fixture Requirements (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-386	Accessibility Modules (Module 10) Special Considerations (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-387	Accessibility Modules (Module 11) Accessibility in Existing Buildings (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-388	Accessibility Modules (Module 12) Customer Service Elements (online)	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(0.5), BO(0.5), BPE(0.5), EPE(0.5), ESI(0.5), FPI(0.5), FPPE(0.5), LPE(0.5), MPE(0.5), MI(0.5), MCPE(0.5), NRIUI(0.5), PI(0.5), PPE(0.5), RBI(0.5), RBO(0.5), REPE(0.5), RIUI(0.5), RMI(0.5), RPE(0.5), RPI(0.5)
BBS2018-389	Hoarding: OMG, What Do I Do Now?	Hoarding Connection of Cuyahoga County	Jeanne Hoban	(216) 373-1686	jhoban@benrose.org	BI(4.0), BO(4.0), BPE(4.0), EPE(4.0), ESI(4.0), FPI(4.0), FPPE(4.0), LPE(4.0), MPE(4.0), MI(4.0), MCPE(4.0), NRIUI(4.0), PI(4.0), PPE(4.0), RBI(4.0), RBO(4.0), REPE(4.0), RIUI(4.0), RMI(4.0), RPE(4.0), RPI(4.0)
BBS2018-390	International Code Council Hearings April 15	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-391	International Code Council Hearings April 16	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)

BBS2018-392	International Code Council Hearings April 17	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-393	International Code Council Hearings April 18	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-394	International Code Council Hearings April 19	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-395	International Code Council Hearings April 20	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-396	International Code Council Hearings April 21	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-397	International Code Council Hearings April 22	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-398	International Code Council Hearings April 23	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(6.0), BO(6.0), BPE(6.0), EPE(6.0), ESI(6.0), FPI(6.0), FPPE(6.0), LPE(6.0), MPE(6.0), MI(6.0), MCPE(6.0), NRIUI(6.0), PI(6.0), PPE(6.0), RBI(6.0), RBO(6.0), REPE(6.0), RIUI(6.0), RMI(6.0), RPE(6.0), RPI(6.0)
BBS2018-403	2011 to 2017 OPC Changes and Updates	BOCONEO / Mario J DiFranco	Mario DiFranco	(440) 840-7332	mdifranco615@aol.com	BO(3.0), MPE(3.0), PPE(3.0), MCPE(3.0), BI(3.0), FPI(3.0), MI(3.0), PI(3.0), NRIUI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), RMI(3.0), RIUI(3.0)
BBS2018-404	Chapter 7 and 8 OBC 2017	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BO(3.0), MPE(3.0), PPE(3.0), EPE(3.0), MCPE(3.0), BI(3.0), FPI(3.0), MI(3.0), PI(3.0), NRIUI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), RMI(3.0)

BBS2018-405	Chapter 9 OBC 2017	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BO(3.0), MCPE(3.0), PPE(3.0), EPE(3.0), MPE(3.0), BI(3.0), FPI(3.0), MI(3.0), PI(3.0), NRIUI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), RMI(3.0)
BBS2018-406	Chapter 10 OBC 2017	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BO(3.0), MCPE(3.0), PPE(3.0), EPE(3.0), MPE(3.0), BI(3.0), FPI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), RMI(3.0)
BBS2018-407	High-Speed Doors and Thermal Performance	Door and Access Systems Manufacturers Assn	Joseph Hetzel	(216) 241-7333	jhetzel@thomasamc.com	BO(1.0), MPE(1.0), EPE(1.0), BI(1.0), RBO(1.0), PPE(1.0), RBI(1.0)
BBS2018-408	Automated Vehicular Gate Systems	Door and Access Systems Manufacturers Assn	Joseph Hetzel	(216) 241-7333	jhetzel@thomasamc.com	BO(1.0), MPE(1.0), EPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-409	Domestic Water Heaters	Hamilton County Planning and Development	Robert Eifert	(513) 946-4530	bob.eifert@hamilton-co.org	BO(1.0), MPE(1.0), PPE(1.0), MCPE(1.0), BI(1.0), MI(1.0), PI(1.0), NRIUI(1.0), RBO(1.0), RPE(1.0), RBI(1.0), RMI(1.0), RIUI(1.0)
BBS2018-410	OPC Venting Methods	Hamilton County Health District	Lisa Humble	(513) 946-7851	lisa.humble@hamilton-co.org	BO(3.0), MPE(3.0), PPE(3.0), BI(3.0), PI(3.0), RBO(3.0), RPE(3.0), RBI(3.0)
BBS2018-411	CSST Piping Systems	Omega Flex	Art Weirauch	(610) 280-4114	artw@moegaflex.net	BO(2.0), MPE(2.0), PPE(2.0), MCPE(2.0), BI(2.0), MI(2.0), PI(2.0), RBO(2.0), RPE(2.0), RBI(2.0), RMI(2.0)
BBS2018-413	OPC Updates Course	Clermont County Public Health	Kevin Jester		ccph@clermontcountyohio.gov	BO(3.0), MPE(3.0), PPE(3.0), PI(3.0), RBO(3.0), RPE(3.0)
BBS2018-414	2017 OMC Overview (Session 1)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), MCPE(1.0), BI(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-415	2017 OMC Overview (Session 2)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), MCPE(1.0), BI(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-416	2017 OMC Overview (Session 3)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), MCPE(1.0), BI(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-417	2017 OMC Overview (Session 4)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.5), MPE(1.5), MCPE(1.5), BI(1.5), MI(1.5), RBO(1.5), RPE(1.5), RBI(1.5)
BBS2018-418	2017 OMC Overview (Session 5)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), MCPE(1.0), BI(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-419	2017 OMC Overview (Session 6)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.5), MPE(1.5), MCPE(1.5), BI(1.5), MI(1.5), RBO(1.5), RPE(1.5), RBI(1.5)
BBS2018-420	2017 OMC Overview (Session 7)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.5), MPE(1.5), MCPE(1.5), BI(1.5), MI(1.5), RBO(1.5), RPE(1.5), RBI(1.5)
BBS2018-421	2017 OMC Overview (Session 8)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), MCPE(1.0), BI(1.0), MI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-422	Hoarding: What Do I Do Now?	Hoarding Connection of Cuyahoga County	Jeanne Hoban	(216) 373-1686	jhoban@benrose.org	
BBS2018-423	Structural Design Loads ASCE 7-16	HalfMoon Education Inc	Doug Chapman	(715) 835-5900	doug@halfmoonseminars.org	BO(7.0), MPE(7.0), BI(7.0), RBO(7.0), RPE(7.0), RBI(7.0)
BBS2018-424	IFC High-Piled Combustible Storage	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BO(6.0), BI(6.0), FPI(6.0), RBO(6.0), RBI(6.0), FPPE(6.0)

BBS2018-425	Weekly Training 1: Definitions, Use, Occupancy	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-426	Weekly Training 2: Use and Occupancy Special Requirments	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-427	Weekly Training 3: General Building Heights and Area	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-428	Weekly Training 4: Types of Construction	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-429	Weekly Training 5: Fire and Smoke Protection Features (Part 1)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-430	Weekly Training 6: Fire and Smoke Protection (Part 2)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-431	Weekly Training 7: Interior Finishes	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-432	Weekly Training 8: Fire Protection Systems (Part 1)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-433	Weekly Training 9: Fire Protection Systems (Part 2)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-434	Weekly Training 10: Means of Egress (Part 1)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-435	Weekly Training 11: Means of Egress (Part 2)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-436	Weekly Training 12: Accessibility (Part 1)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-437	Weekly Training 13: Accessibility (Part 2)	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-438	Weekly Training 14: Interior Environment	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-439	Weekly Training 15: Energy Efficiency	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-440	Weekly Training 16: Exterior Walls	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-441	Weekly Training 17: Foundations	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-442	Weekly Training 18: Floors	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-443	Weekly Training 19: Wall Construction	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), PPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-444	Weekly Training 20: Roof Assemblies and Rooftop Structures	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-445	Weekly Training 21: Special Inspections	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)

BBS2018-446	Weekly Training 22: Glass and Glazing	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-447	Weekly Training 23: Special Construction	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-448	Weekly Training 24: Safeguards During Construction	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-449	Weekly Training 25: Existing Buildings	City of Columbus (Cliff Honeycutt / Bob Schutz/Janet Rusavowsky)	Bob Schutz	(614) 395-9689	rjschutz@columbus.gov	BO(1.0), MPE(1.0), BPE(1.0), BI(1.0), RBO(1.0), RPE(1.0), RBI(1.0)
BBS2018-450	Legal Aspects of Code Enforcement	COCOA (Mike Poirier)	Mike Poirier	(614) 830-2045	cocoaonline@gmail.com	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), FPI(3.0), FPPE(3.0), LPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0), RPI(3.0)
BBS2018-451	Significant Changes to the NEC 2017 (Part A1)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-452	Significant Changes to the NEC 2017 (Part A2)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-453	Significant Changes to the NEC 2017 (Part A3)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-454	Significant Changes to the NEC 2017 (Part B1)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-455	Significant Changes to the NEC 2017 (Part B2)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-456	Significant Changes to the NEC 2017 (Part B3)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-457	Significant Changes to the NEC 2017 (Part C1)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-458	Significant Changes to the NEC 2017 (Part C2)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-459	Significant Changes to the NEC 2017 (Part C3)	Electrical Trades Center	Trent Parker	(614) 463-5282	parker@electricaltrades.org	ESI(3.5)
BBS2018-460	Automatic Sprinkler Systems: Requirements	Associated Consulting Solutions LLC	Jerry Flanik	(216) 256-3556	skillbuilder64@aol.com	BI(3.0), BO(3.0), BPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RPE(3.0)
BBS2018-461	2017 Ohio Mechanical & Fuel Gas Code Highlights	Associated Consulting Solutions LLC	Jerry Flanik	(216) 256-3556	skillbuilder64@aol.com	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-462	2017 OMC - Design, Plan Review & Inspection	Associated Consulting Solutions LLC	Jerry Flanik	(216) 256-3556	skillbuilder64@aol.com	BI(3.0), BO(3.0), BPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), RBI(3.0), RBO(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-463	SI Structural Steel and Bolting Inspector Test Academy	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BO(15.0), BI(15.0)

BBS2018-464	ADA Accessibility in the 2017 Ohio Building Code	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-465	Complaints, Investigations and Audits: The BBS Investigatory Process	BBS	Meg Foley	(614) 644-2613	mfoley@com.state.oh.us	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-466	Inspector Skills	Associated Consulting Solutions LLC	Jerry Flanik	(216) 256-3556	skillbuilder64@aol.com	BI(3.0), BO(3.0), BPE(3.0), EPE(3.0), ESI(3.0), FPI(3.0), FPPE(3.0), MPE(3.0), MI(3.0), MCPE(3.0), NRIUI(3.0), PI(3.0), PPE(3.0), RBI(3.0), RBO(3.0), REPE(3.0), RIUI(3.0), RMI(3.0), RPE(3.0)
BBS2018-467	Chapter 11 of the 2017 OBC	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BO(3.0), MPE(3.0), BPE(3.0), PPE(3.0), EPE(3.0), MCPE(3.0), FPPE(3.0), BI(3.0), FPI(3.0), MI(3.0), PI(3.0), NRIUI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), RMI(3.0), RIUI(3.0)
BBS2018-468	Chapter 34 of the 2017 OBC	Dabdoub & Associates LLC	Majed Dabdoub	(513) 208-2056	majed@dabdoub.net	BO(3.0), MCPE(3.0), BPE(3.0), PPE(3.0), EPE(3.0), MPE(3.0), FPPE(3.0), BI(3.0), FPI(3.0), MI(3.0), PI(3.0), NRIUI(3.0), RBO(3.0), RPE(3.0), RBI(3.0), RMI(3.0), RIUI(3.0)
BBS2018-469	Leadership Skills Institute	ICC	Laura Morris	(888) 422-7233	lmorris@iccsafe.org	BI(12.0), BO(12.0), BPE(12.0), EPE(12.0), FPI(12.0), FPPE(12.0), LPE(12.0), MPE(12.0), MI(12.0), MCPE(12.0), PI(12.0), PPE(12.0), RBI(12.0), RBO(12.0), RMI(12.0), RPE(12.0)