

**Ohio Department of Commerce
Division of State Fire Marshal
Bureau of Underground Storage Tank
Regulations**

**Petroleum Underground Storage Tank
2012 Annual Report**

This Underground Storage Tank (UST) annual report is being provided as required by the Federal Energy Act of 2005 "Public Records Provision" for the reporting period of October 1, 2011 through September 30, 2012.

Public Record Post Date: **April 2, 2013**

Ohio UST Statistics and Information for the Reporting Period

Inspection period: October 1, 2011 through September 30, 2012

Number of facilities inspected: **2,877**

Percent of UST facilities inspected with release prevention (corrosion protection, spill and overfill) and release detection requirements: **89%**

Total number of UST facilities at the end of the reporting period: **7,596**

Total number of underground storage tanks at the end of the reporting period: **22,144**

Summary Information for Releases

Total new UST releases that took place during the reporting period: ***72**

Release reporting period: October 1, 2011 through September 30, 2012

Source	Cause													
	Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	0	0%	0	0%	1	11%	1	11%	0	0%	0	0%	7	78%
Piping	0	0%	0	0%	8	44%	0	0%	0	0%	0	0%	10	56%
Dispenser	0	0%	0	0%	7	54%	0	0%	0	0%	1	8%	5	38%
Submersible Turbine Pump	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	3	100%
Delivery Problem	1	%	2	100%	0	0%	0	0%	0	0%	0	0%	0	0%
Other	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Unknown	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	25	100%

SOURCE	NUMBER	PERCENTAGE
Tank	9	13%
Piping	18	25%
Dispenser	13	18%
STP	3	4%
Delivery	3	4%
Other	0	0%
Unknown	25	35%

Note: Only UST releases that are identified to have taken place during the reporting period have been included in this report. All “release” and “source” data was entered into the Ohio Tank Tracking & Environmental Review (OTTER) data base by (BUSTR) staff. The “Grant Guidelines To States For Implementing The Public Information Provision of The Energy Policy Act Of 2005” were followed by the BUSTR staff for classifying all entered data. Information was gathered from reports and information submitted by consultants, inspectors, the Ohio Environmental Protection Agency and BUSTR certified inspectors and installers. No attempt to verify information from consultants has been done. All data used to compile this report has been retrieved from the OTTER data base. * There are **12** multiple sources identified for the reported **72** releases.

Site specific release information used in this report can be obtained by contacting the Bureau of Underground Storage Tank Regulations by telephone at (614) 752-7938 or by e-mail at websfm@com.state.oh.us.

Updated April 2, 2013

Bureau of Underground Storage Tank Regulations • 8895 East Main Street • P.O. Box 687 • Reynoldsburg, Ohio 43068-9009 • www.com.ohio.gov • (614) 752-8963 • (800) 686-2878